

# N-51 AUTOMOTIVE PTE LTD

\*Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TP 1st Cap.  
 Hui Rong

## TAX INVOICE

BERNARD CHUA KEE CHANG  
 BLK 945 TAMPINES AVE 4 #07-328  
 SINGAPORE 520945

Repair Code : CLM17408  
 Date in : 06/10/2022  
 Vehicle Num. : SKU8751Y  
 Model : HONDA CIVIC 1.6L AUTO  
 Chassis/Eng# : JHMFD4620AS200181/R16A15000243

Contact : 92220358

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Repair</i>	1	610.70	<i>x</i> 610.70
REAR BOOTLID '1.6' EMBLEM	1	21.00	<i>✓</i> 21.00
REAR BOOTLID 'CIVIC' EMBLEM	1	31.10	<i>✓</i> 31.10
REAR BOOTLID 'H' LOGO	1	28.70	<i>✓</i> 28.70
REAR BOOTLID 'I-VTEC' EMBLEM	1	36.20	<i>✓</i> 36.20
REAR BOOTLID RH REFLECTOR <i>Cracked</i>	1	145.10	<i>✓</i> 145.10
REAR BUMPER <i>Deformed.</i>	1	668.00	<i>✓</i> 668.00
REAR BUMPER RH INNER SEAL COVER <i>Not new</i>	1	21.50	<i>x</i> 21.50
REAR BUMPER SIDE RETAINER L/R <i>RH Damaged.</i>	2	16.90	<i>16.90</i> <del>33.80</del>
REAR END PANEL <i>Repair</i>	1	498.70	<i>x</i> 498.70
REAR RH FENDER <i>Cracked</i>	1	778.50	<i>✓</i> 778.50
REAR RH FENDER AIR VENT <i>Cracked.</i>	1	29.30	<i>✓</i> 29.30
REAR RH FENDER INNER TRIM GARNISH <i>Deformed</i>	1	175.90	<i>✓</i> 175.90
REAR RH TAILLAMP <i>Cracked.</i>	1	256.20	<i>✓</i> 256.20
REAR RH TAILLAMP LOWER BRACKET <i>Not new</i>	1	15.90	<i>x</i> 15.90
REAR RH TAILLAMP PANEL <i>Repair</i>	1	75.70	<i>x</i> 75.70
REAR WINDSCREEN GLASS MOULDING <i>Not new</i>	1	58.00	<i>✓</i> 58.00
		<i>2244.90</i>	
		<i>1755.92</i>	

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

**BERNARD CHUA KEE CHANG**  
 BLK 945 TAMPINES AVE 4 #07-328  
 SINGAPORE 520945

**TAX INVOICE**

Repair Code : CLM17408  
 Date in : 06/10/2022  
 Vehicle Num. : SKU8751Y  
 Model : HONDA CIVIC 1.6L AUTO  
 Chassis/Eng# : JHMFD4620AS200181/R16A15000243

Contact : 92220358

	Subtotal before discount			3,484.30
Percentage discount	20%			696.86
	<b>Sub-total 1</b>			<b>2,787.44</b>
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	<i>new</i>	1	50.00	<del>50.00</del>
REAR BUMPER CLIPS - SET	<i>new</i>	1	50.00	<del>50.00</del>
REAR BUMPER LOWER LID SPOILER	<i>Torn</i>	1	900.00	<del>900.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>new</i>	1	30.00	<del>30.00</del>
REAR RH FENDER INNER TRIM GARNISH CLIPS - SET	<i>new</i>	1	50.00	<del>50.00</del>
REAR RH TAILLAMP PANEL SEALANT	<i>new</i>	1	50.00	<del>50.00</del>
REAR WINDSCREEN GLASS SEALANT	<i>new</i>	1	60.00	<del>60.00</del>
	Subtotal before discount			1,190.00
Percentage discount	0%			0.00
	<b>Sub-total 2</b>			<b>1,190.00</b>
	<b>Parts-total</b>			<b>3,977.44</b>

**LABOUR**

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.				<del>60.00</del>
To remove and refit rear windscreen(to FR)				<del>150.00</del>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)				<del>140.00</del>
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.				<del>1,200.00</del>
To remove and reinstall exhaust pipe.				<del>80.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

BERNARD CHUA KEE CHANG  
 BLK 945 TAMPINES AVE 4 #07-328  
 SINGAPORE 520945

Contact : 92220358

**TAX INVOICE**

Repair Code : CLM17408  
 Date in : 06/10/2022  
 Vehicle Num. : SKU8751Y  
 Model : HONDA CIVIC 1.6L AUTO  
 Chassis/Eng# : JHMFD4620AS200181/R16A15000243

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.  
 To apply anti-rust chemical on repaired and replaced panel.

	1700	<del>600</del> 1,200.00
		<del>60.</del> 80.00
<b>Labour Total</b>		<b>2,910.00</b>
<b>Parts &amp; Labour Total</b>		<b>6,887.44</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

total: 4265.92  
 1/s: 34K.  
 06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

34K.  
 06 Days.