



LEXBUILD AUTO & TRADING PTE. LTD.

74 Sungei Kadut St 1, S 729374 Tel: 63623393 Fax: 63632262 Reg No: 200616456D Email : lexbuildauto@gmail.com

UNITED OVERSEAS INSURANCE LTD
146 Robinson Road
#02-01 UOI Building
Singapore 068909

252
1400
1652

Date: 03/10/2022

Our Ref: PC1119E/SUN-GEE/2209

Your Ref: SLA9298B

Attn : Claim Dept

Dear Sir, Ma'am

RE: Estimate Repair Cost for Vehicle PC1119E

Traffic Accident on 25.09.2022 Involving PC1119E & SLA9298B At CTE EXIT 7D TOWARDS BALESTIER ROAD.

S/N	Qty	Particular	Unit Price	Amount S\$
1	1	LHS 1st Luggage Compartment Panel repair	1,050.00	1,050.00 XR
2	1	LHS 2nd Luggage Compartment Panel repair	1,050.00	1,050.00 XR
3	1	Rear RHS Tyre Compartment Panel repair	950.00	950.00 XR
4	1	Lugage Compartment Lock sun / (1pc)	280.00	560.00 X
				3,610.00

Labour Charges :-

- 1) To jack/knock/straighten all necessary parts including repairing & changing of all damaged parts and align same.
- 2) To putty & spray painting on LHS 1st & 2nd Luggage Compartment Panel, Rear RHS Tyre Compartment Panel and affected accident parts.

1400 { 600 1,200.00
800 1,500.00

Total S\$: 6,310.00
GST 7% S\$: 441.70
Amount Due S\$: 6,751.70

Note : This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress.

Yours Sincerely,



Alvin Tey
Lexbuild Auto & Trading Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 90010068
4 days
P/P
10/10/22 @ 1515
Resy after repair
Resy luggage lock