

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 06 Oct 2022)

Parts: M1-MPV

TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK554T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / <i>DR</i>	0.00	0.00	*250.00 F ✓
2	10		*REAR BUMPER CLIP / <i>DR</i>	0.00	0.00	*20.00 F ✓
3	2		*REAR BUMPER RETAINER / <i>GR</i>	0.00	0.00	*80.00 F ✓
4	1		*REAR BUMPER REFLECTOR RH / <i>GR</i>	0.00	0.00	*40.00 F ✓
5	1		*REAR PARKING SENSOR / <i>GR</i>	0	0.00	*180.00 FS ✓ <i>nett</i>
6	1		*REAR TAILLAMP RH / <i>GR</i>	0.00	0.00	*130.00 F ✓
7	1		*REAR TAILLAMP RETAINER / <i>GR</i>	0.00	0.00	*40.00 F ✓
8	1		*REAR TAILLAMP RETAINER / <i>GR</i>	0.00	0.00	*520.00 F ✓
9	2		*REAR BOOT LID / <i>GR</i>	0.00	0.00	*80.00 F ✓
10	1		*REAR BOOT HINGE / <i>GR</i>	0.00	0.00	*150.00 F ✓
11	1		*REAR BOOT LOCK / <i>GR</i>	0.00	0.00	*280.00 F ✓
12	1		*REAR BOOT TRIMBOARD / <i>GR</i>	0.00	0.00	*40.00 F ✓
13	1		*REAR BOOT EMBLEM / <i>GR</i>	0.00	0.00	*40.00 F ✓
14	1		*REAR BOOT VALVEMATIC LOGO / <i>GR</i>	0.00	0.00	*130.00 F ✓
15	2		*REAR BOOT CHROME / <i>GR</i>	0.00	0.00	*260.00 F ✓
16	1		*REAR BOOT LAMP / <i>GR</i>	0.00	0.00	*130.00 F ✓
17	1		*REAR BOOT RUBBER / <i>GR</i>	0.00	0.00	*190.00 F ✓
18	1		*REAR END PANEL / <i>GR</i>	0.00	0.00	*120.00 F ✓
19	1		*REAR END PANEL TOP GARNISH / <i>GR</i>	0.00	0.00	*450.00 F ✓
20	1		*REAR WINDSCREEN / <i>GR</i>	0.00	0.00	*240.00 F ✓
21	1		*REAR WINDSCREEN INNER TRIM RH / <i>GR</i>	0	0.00	*40.00 FS ✓ <i>nett</i>
22	1		*REAR WINDSCREEN SEALANT / <i>GR</i>	0.00	0.00	*150.00 F ✓
23	1		*REAR WINDSCREEN MOULDING / <i>GR</i>	0.00	0.00	*100.00 F X
24	2		*REAR WINDSCREEN SIDE MOULDING / <i>GR</i>	0	0.00	*35.00 FS ✓ <i>nett</i>
25	1		*REAR NUMBER PLATE / <i>GR</i>	0.00	0.00	*450.00 F ✓
26	1		*REAR FENDER RH / <i>GR</i>	0.00	0.00	*450.00 F ✓
27	1		*REAR FENDER GLASS WITH MOULDING / <i>GR</i>	0	0.00	*40.00 FS ✓ <i>nett</i>
28	1		*REAR FENDER GLASS SEALANT / <i>GR</i>	0.00	0.00	*450.00 F ✓
29	1		*REAR FENDER INNER TRIM / <i>GR</i>	0.00	0.00	*450.00 F ✓
30	1		*REAR SPARETYRE PANEL / <i>GR</i>	0.00	0.00	*350.00 F X
31	1		*REAR SPARETYRE BOARD / <i>GR</i>	0.00	0.00	*450.00 F X
32	1		*REAR WIPER ARM / <i>GR</i>	0.00	0.00	*70.00 F ✓
33	1		*REAR WIPER BLADE / <i>GR</i>	0.00	0.00	*22.00 F ✓
33	1		*REAR WIPER MOTOR / <i>GR</i>	0.00	0.00	*280.00 F X

F=Franchise part. S=SpcNett.

4782

+10%

5260.20

nett - 295

+ Margin on L,N Items 10.00% (S\$)

Sub Total (S\$)

6,257.00

596.20

Total Parts (S\$)

6,853.20

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
new miscellaneous items selected.

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items		
1 TO REMOVE & REFIX SEATS	New ?	150.00 80
2 TO KNOCK, STRAIGHTEN CHASSIS,WELD,REMOVE & FIX ON ABOVE PARTS	New	1,200.00 ✓
3 TO REMOVE & FIX REAR WINDSCREEN	New 175	120 ✓ 150.00
4 TO REMOVE & REFIX TRIM	New 80	✓ 200.00
5 TO PUTTY & SPRAY PAINTING ON CHASSIS,RR FENDER LH & AFFECTED AREAS	New 1000	✓ 1,400.00
	2480	Gross Labour Cost (\$\$) 3,100.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Stew (LKK)
7/10/22, 12:00
m IL
LIS
L7 AR 4
10 45

8035.20

L/S - 6428.16
= 6450

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: