

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 25.10.2022

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **EV1811U**
MODEL : **HYUNDAI AVANTE**
DATE OF ACCIDENT : 03.10.2022
TIME OF ACCIDENT : 21:10 HRS

Xiao Tony.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 459.40	\$ 459.40
2	REAR BUMPER LAMP <i>me h</i>	2	\$ 201.50	\$ 403.00
3	REAR BUMPER LAMP WIRE HARNESS <i>3x1</i>	1	\$ 121.00	\$ 121.00
4	REAR BUMPER NUMBER PLATE LAMP <i>me</i>	2	\$ 28.00	\$ 56.00
5	REAR BUMPER CENTRE (BLACK) <i>me</i>	1	\$ 353.50	\$ 353.50
6	REAR BUMPER RETAINER <i>me</i>	2	\$ 29.40	\$ 58.80
7	REAR BUMPER REINFORCEMENT <i>3x1</i>	1	\$ 294.80	\$ 294.80
8	REAR BUMPER REINFORCEMENT BRACKET <i>me</i>	2	\$ 5.00	\$ 10.00
9	REAR BUMPER BRACKET <i>Not all</i>	5	\$ 78.60	\$ 393.00
10	REAR BUMPER SIDE INNER LOWER GARNISH <i>2</i>	1	\$ 37.20	\$ 37.20
11	REAR FENDER INNER COWLING (REAR)	2	\$ 60.00	\$ 120.00
12	REAR FENDER INNER TRIM	2	\$ 208.00	\$ 416.00
13	TAILLAMP	2	\$ 1,052.10	\$ 2,104.20
14	BOOTLID TOP LOCK <i>NP</i>	1	\$ 116.20	\$ 116.20
15	BOOTLID LOWER LOCK <i>me</i>	1	\$ 16.00	\$ 16.00
16	BOOTLID WEATHER STRIP	1	\$ 92.50	\$ 92.50
17	REAR END PANEL	1	\$ 454.60	\$ 454.60
18	REAR END PANEL TOP GARNISH	1	\$ 59.80	\$ 59.80
19	REAR FLOOR PANEL TOP BOARD	1	\$ 219.10	\$ 219.10

TOTAL PRICE \$ 5,785.10
LESS 20% \$ 1,157.02
SUB TOTAL PRICE \$ 4,628.08

871.70
697.36

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **EV1811U**
 MODEL : **HYUNDAI AVANTE**
 DATE OF ACCIDENT : 03.10.2022
 TIME OF ACCIDENT : 21:10 HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPCIEAL TYPE) <i>new</i>	1	\$ 180.00	\$ 180.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER LID (SPECIAL TYPE) <i>Delid</i>	1	\$ 1,800.00	\$ 1,800.00
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
5	REAR FENDER INNER COWLING CLIP (SET) <i>2</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>1</i>	1	\$ 80.00	\$ 80.00
7	REAR END PANEL TOP GARNISH CLIP (SET) <i>1</i>	1	\$ 40.00	\$ 40.00
8	REAR END PANEL INSULATION SEALANT <i>✓</i>	1	\$ 150.00	\$ 150.00
9	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 2,670.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	500
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	+
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **EV1811U**
MODEL : **HYUNDAI AVANTE**
DATE OF ACCIDENT : 03.10.2022
TIME OF ACCIDENT : 21:10 HRS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	✓
---	--	-----------	---

780

TOTAL \$ 3,790.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,298.08
TOTAL LABOUR COST : \$ 3,790.00
TOTAL REPAIR COST : \$ 11,088.08

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Cj
1/s 26/10/22
02 Days

total: 2307.36
1/s: 1.8k

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--