



**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

**Date Generated : 07/11/2022**
**User ID                      PohSuan**
**Section A - Accident Details**

Registration Number	SHB1336U
Case Reference Number	TAX/10/22/2012
Registration Date	28/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHAMAD BOUZI BIN SULAIMAN
Type of Accident	Rear To Head
Accident Date and Time	4/10/2022 4:30 PM
Accident Reported Date and Time	5/10/2022 12:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116487
Special Instruction to ARC, if any	FRONT RIGHT PORTION OF BUMPER
Prepared Date and Time	5/10/2022 2:33 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$7,549.96	\$452.21
Total Other Cost	\$380.00	\$0.00
<b>TOTAL COST</b>	<b>\$9,163.96</b>	<b>\$852.21</b>
<b>Lump Sum Total</b>	<b>\$9,150.00</b>	<b>\$850.00 (L/S)</b>
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Rasul(LKK) / ERGO</b>
ARC / Surveyor Sign Off Date	<b>07/10/2022 7:58 AM</b>	<b>06/10/2022 4:59 PM</b>
Signature		
Remarks		lump sum repair / resurvey after repair

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2211-0038	Invoice Number	
Quotation Date	07.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$200.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$558.00</b>	<b>\$200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$380.00</b>	<b>\$0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.23	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		52127479 07	COVER, FR BUMPER RH	0.00	\$31.80	0.00	\$0.00	Replace	Not Given
		52114471 90	BRACKET, FR BUMPER	0.00	\$111.80	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$773.90	0.00	\$0.00	Replace	Not Given
		52611471 40	ABSORBER, FR BUMPER	0.00	\$85.90	0.00	\$0.00	Replace	Not Given
		52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given
		52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given
		75310470 60	EMBLEM ASSY FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace
		53395470 40	SEAL, HOOD TO FR END	0.00	\$55.80	0.00	\$0.00	Replace	Not Given
		53112472 40	GRILLE, RADIATOR	0.00	\$183.90	0.00	\$0.00	Replace	Not Given
		53101470 80	GRILLE SUB-ASSY	0.00	\$374.40	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$9.50	0.00	\$0.00	Replace	Not Given
		81210470 20	LAMP ASSY, FOG, RH	0.00	\$1,029.90	0.00	\$0.00	Replace	Not Given
		81145476 91	UNIT , HEADLAMP , RH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given

✓  
 X  
 X  
 X  
 X  
 ✓  
 X  
 X  
 X  
 X  
 X  
 ✓  
 X  
 X  
 X  
 X  
 ✓  
 X  
 X  
 X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/11/2022

User ID                      PohSuan

		81185476 91	UNIT , HEADLAMP , LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given	X
		81016476 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$1,039.90	0.00	\$0.00	Replace	Not Given	X
		53205479 00	SUPPORT S/A UPPER,	0.00	\$408.50	0.00	\$0.00	Replace	Not Given	X
		53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>					<b>\$10,965.10</b>		<b>\$565.26</b>			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	565.26	
	-20%	
	452.21	L/S \$850/-
+	200.00	
+	200.00	
	852.21	