

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0782/2022/EQ
DATE : 8-Sep-22
WIP : 41041

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/10/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian

5 days exclude 1 Sunday

Johnny Boo 11 Dec 22

OWNER'S NAME : MR WONG EE KAY GEOFFREY
ADDRESS : 33 BIN TONG PARK
SINGAPORE 269814

TELEPHONE : HP +65 97236646
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220082881
VEHICLE NO : **SNH 25 X**
MODEL CODE : AUDI Q7 3.0 TFSI QU TIPTR
MODEL YEAR : 28/7/2022
ENGINE NO : DCB 531578
CHASSIS NO : WAUZZZ4MXD022969
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Sep-22
PLACE OF ACCIDENT : LENG KEE ROAD & ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 25 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S WING MIRROR (For door respray.)	S/N \$	900.00	\$ 300.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	\$ 600.00
4	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR COVERS, DOOR HANDLES, RHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS.	\$	7,000.00	\$ 1,900.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,452.00	\$ 2,992.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 25 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 5,466.00	
2	FRONT OUTER DOOR SEAL	1	\$ 282.00	
3	BONDING AGENT	1	\$ 51.00	
4	CLEANING SOLUTION	1	\$ 74.00	
5	APPLICATOR	1	\$ 9.00	
6	FRONT DOOR CATCH - RH	1	\$ 137.00	
7	FRONT DOOR COVER - RH	1	\$ 963.00	
8	REAR DOOR - RH	1	\$ 5,708.00	
9	BONDING AGENT	1	\$ 51.00	
10	CLEANING SOLUTION	1	\$ 74.00	
11	APPLICATOR	1	\$ 9.00	
12	REAR DOOR CATCH - RH	1	\$ 137.00	
13	REAR OUTER DOOR SEAL - RH	1	\$ 213.00	
14	REAR WEATHER STRIP	1	\$ 282.00	
15	REAR DOOR COVER - RH	1	\$ 883.00	\$ 706.00
16	REAR DOOR WHEEL COVER - RH	1	\$ 201.00	\$ 160.40
17	REAR WHEEL COVER - LH / RH	2	\$ 770.00	\$ 308.00
18	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 15,710.00	\$ 1,174.40
TOTAL LABOUR CHARGES			\$ 12,452.00	\$ 2,992.00
GRAND TOTAL			\$ 28,162.00	\$ 4,166.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-05/12/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT