

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

TP Ergo.
Xiao Chen.

WBA8G32090A062582

SKF3337Y BMW 320 ESTATE

No	Qty	Parts Description	Estimated Parts Price
1	1	Front sport bumper with spoiler complete assy <i>Behind</i>	\$ 3,650.00 2000(SN)
2	2	Front bumper retainer <i>3 new</i>	\$ 225.00 x
3	2	Front bumper bracket <i>3 new</i>	\$ 128.00 +.
4	1	Front bumper left inner upper garnish <i>3 new</i>	\$ 165.00 +.
5	1	Front bumper left inner lower garnish <i>3 new</i>	\$ 165.00 +.
6	1 set	Front support panel inner garnish <i>3 new</i>	\$ 160.00 x
7	1	Front bumper reinforcement	\$ 625.00 +.
8	1	Front bumper sponge <i>cracked.</i>	\$ 163.00 ✓
9	1	Front bumper tow cover <i>new</i>	\$ 88.00 x
10	1	Front bumper centre logo <i>new</i>	\$ 128.00 75.
11	1	Front left LED headlamp <i>cracked.</i>	\$ 3,250.00 ✓
12	1	Front left LED headlamp module <i>3 new</i>	\$ 1,250.00 x
13	1	Front left LED headlamp bracket <i>3 new</i>	\$ 125.00 x.
14	1	Front bonnet assy <i>new</i>	\$ 2,350.00 x.
15	1	Front fog lamp <i>cracked.</i>	\$ 290.00 ✓
16	1	Front fog lamp garnish <i>cracked.</i>	\$ 85.00 ✓
17	2	Front bonnet hinges <i>3 new</i>	\$ 160.00 x
18	1	Front bonnet insulator <i>3 new</i>	\$ 280.00 x
19	2	Front bonnet lock catch <i>3 new</i>	\$ 108.00 x
20	1 set	Front bonnet lock mechanism <i>new</i>	\$ 385.00 x
21	2	Front kidney grille assy <i>LT cracked</i>	\$ 650.00 215.
22	1	Front kidney grille inner air vent assy <i>3 new</i>	\$ 350.00 +
23	1	Front kidney grille inner garnish assy <i>3 new</i>	\$ 205.00 +
24	1	Front left air duct vent <i>Behind</i>	\$ 175.00 ✓
25	1	Front left fender <i>Repair</i>	\$ 1,395.00 x. 4253
26	2	Front left fender inner cowling <i>new</i>	\$ 325.00 x.
27	1	Front left side lower cover <i>new</i>	\$ 185.00 x. SN: 2000
			\$ 17,065.00
Less 5%			\$ 853.25
			\$ 16,211.75
<u>Special Nett Items</u>			
1	12	Front bumper clips <i>new</i>	\$ 50.00 30.
2	1 set	Front bumper parking sensor <i>new</i>	\$ 1,200.00 +
3	1 set	Front bumper parking sensor wire harness <i>new</i>	\$ 450.00 +
4	1	Front no plate with garnish <i>new</i>	\$ 100.00 +
5	6	Front kidney grille assy clips <i>new</i>	\$ 50.00 20.
6	1 set	Front bonnet insulator clips <i>new</i>	\$ 50.00 x
7	8	Front left fender inner cowling clips <i>new</i>	\$ 40.00 x.
			\$ 1,940.00
Total parts			\$ 18,151.75

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKF3337Y BMW 320 ESTATE

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front, front left affected area and replace front and front left damaged parts.	\$ 1,200.00 400
2	To putty and spray painting front and front left portion.	\$ 1,200.00 400.
3	To check wiring and focus front headlamp.	\$ 50.00 30.
4	To remove and install front bonnet lock mechanism.	\$ 80.00 x
5	To apply anti rust proofing to front affected area.	\$ 140.00 30.
6	Towing service.	\$ 120.00 x.
Total labour :		\$ <u>2,790.00</u>

Total parts : \$ 18,151.75

Total labour : \$ 2,790.00

Total repair cost : \$ 20,941.75

total: 6950.35

L/S: S.S.K.

OH Days

S.S.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: