



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET		Ref: CC4/ASM22009913/Kpa3q2 Date: 14/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7152H	Veh. Inspected	SGF 6888B
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04C9G	Excess (\$)	0.00
Assign From		Assign Date	07/10/2022
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 216I (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBA2X920707E11053	Colour	METALLIC PEARL WHITE
Odometer	19842 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R17	MICHELIN	8 mm
L/H Front Tyre	205/55 R17	MICHELIN	8 mm
R/H Rear Tyre	205/55 R17	MICHELIN	8 mm
L/H Rear Tyre	205/55 R17	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/10/2022	Inspection Date	07/10/2022
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	