


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Not Withheld
11 Sep & 20 Oct
Prework After Paint
3 days

Make/Model: BMW 216i
 Engine/Chassis No.: WBA2X920707E11053
 Date of accident:
 Damaged area: N/S Rear

Date: 07/10/2022
 Claim Type: TP
 VRN: SGF6888B



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear fender n/s	1	\$ 1,078.00	\$ 1,078.00
2	Rear fender cowling n/s	1	\$ 228.00	\$ 228.00
3	Rear fender glass moulding n/s	1	\$ 119.00	\$ 119.00
4	Rear shock absorber n/s	1	\$ 589.00	\$ 589.00
5	Rear shock absorber mounting n/s	1	\$ 167.00	\$ 167.00
6	Rear lower arm n/s	1	\$ 387.00	\$ 387.00
7	Rear wheel carrier n/s	1	\$ 594.00	\$ 594.00
8	Rear wheel knuckle bearing n/s	1	\$ 196.00	\$ 196.00
9	Rear wheel hub n/s	1	\$ 245.00	\$ 245.00
10	Rear fender inner trim n/s	1	\$ 398.00	\$ 398.00
11	Rear bumper	1	\$ 1,164.00	\$ 1,164.00
12	Rear bumper side carrier n/s	1	\$ 183.00	\$ 183.00
13	Rear lower link n/s	1	\$ 216.00	\$ 216.00
14	Rear track control arm n/s	1	\$ 339.00	\$ 339.00
15	Rear roll over strut n/s	1	\$ 475.00	\$ 475.00
16	Rear control arm n/s	1	\$ 445.00	\$ 445.00
17	Taillamp n/s	1	\$ 645.00	\$ 645.00
18	Taillamp lower bracket n/s	1	\$ 54.00	\$ 54.00
19	Rear bumper lower trim moulding	1	\$ 152.00	\$ 152.00
20	Rear bumper side sensor holder n/s	1	\$ 25.00	\$ 25.00
Subtotal				\$ 7,699.00
List discount				5.00%
Total				\$ 7,314.05

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear alloy wheel n/s	1	\$ 550.00	\$ 550.00
2	Rear tyre n/s	1	\$ 280.00	\$ 280.00
3	Rear fender inner trim board clips n/s	10	\$ 5.50	\$ 55.00
4	Rear fender sealant n/s	1	\$ 80.00	\$ 80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Repair Estimate

5	Rear fender cowling clips n/s	nn	10	\$ 5.50	\$ 55.00	X
6	Rear fender glass sealant n/s	nn	1	\$ 100.00	\$ 100.00	X
7	Rear bumper clips	nn	12	\$ 5.50	\$ 66.00	✓
8	Rear bumper side sensor n/s	nn	1	\$ 280.00	\$ 280.00	X
9	Sundries		1	\$ 50.00	\$ 50.00	
Total					\$ 1,516.00	

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	Supply spray paint materials and necessary items to respray affected area / panel.	5	\$ 1,000.00
3	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ nn 50.00
4	To rust proof all affected portions after repair.	0.5	\$ nn 100.00
5	To remove and refit interior upholstery, inner trim, inner garnish, mouldings to facilitate repair.	1	\$ nn 200.00
6	To remove and refit n/s rear undercarriage for replacement of parts.	1	\$ nn 200.00
7	To conduct computerized wheel alignment.	0.75	\$ 150.00
8	To remove and refit n/s rear fender glass to facilitate repair work.	0.75	\$ nn 150.00
Total labour			\$ 3,050.00

Estimate Grand Total	\$ 11,880.05
-----------------------------	---------------------

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from insurance Company
 Acknowledged by Repairer
 Signature:
 Date: