



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 606B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	BUCKLED / CRACKED	1,995.00	1,248.40
1	REAR BUMPER LOWER (CONSISTENT)	DENTED / CUT	744.00	744.00
1	REAR BUMPER LOWER SPONGE (CONSISTENT)	CRACKED	268.00	138.10
2	REAR BUMPER SIDE RETAINER @\$118.00 (CONSISTENT)	SERVICEABLE	236.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	475.70	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$109.00 (CONSISTENT)	TO REPAIR SEE LABOUR	218.00	-
2	REAR BUMPER SENSOR HOLDER @\$26.40 (CONSISTENT)	NOT NECESSARY	52.80	-
	LESS 10% DISCOUNT		-398.95	-213.05
			3,590.55	1,917.45
<u>NETT ITEMS</u>				
2	REVERSE SENSOR (FACTORY ORIGINAL) @\$490.80 (N) (CONSISTENT)	SHORTED	981.60	981.60
	LESS 10% DISCOUNT		-	-98.16
			981.60	883.44
<u>SPECIAL NETT ITEMS</u>				
12	REAR BUMPER CLIPS @\$5.50 (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			146.00	66.00
<u>LABOUR</u>				
	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION ,TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR BUMPER REINFORCEMENT BRACKET.		1,200.00	200.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS.		150.00	20.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL.		1,000.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR .	NOT NECESSARY	100.00	-
			2,450.00	470.00
GRAND TOTAL			7,168.15	3,336.89
RECOMMENDED COST OF REPAIRS				3,336.89

Report Ref No. CC4/ASM22009915/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.