



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN:YVONNE

Ref: CC4/ASM22009915/Kpa3q2

Date: 19/04/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2442P	Veh. Inspected	SKD 606B
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M04CC9	Excess (\$)	0.00
Assign From		Assign Date	07/10/2022

2. Vehicle Particulars & Condition

Make & Model	LEXUS IS300H (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	JTHBH1D2205088392	Colour	METALLIC PEARL WHITE
Odometer	3969 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	BRIDGESTONE	9 mm
L/H Front Tyre	235/45 R18	BRIDGESTONE	9 mm
R/H Rear Tyre	235/45 R18	BRIDGESTONE	9 mm
L/H Rear Tyre	235/45 R18	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/10/2022	Inspection Date	07/10/2022
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**