

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M046OQ Date: 17th July 2023

Our Ref: CS3/ASM22006686/Dvp3m4-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard #48-01 Marina Bay Financial Centre Tower 2 Singapore 018983 (The Motor Claims Department)

Attn: Teo Kitty

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMF 4959Y INSURED VEHICLE: SLU 786M ACCIDENT DATE: 14/07/2022

We thank you for your instruction on 05/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMF 4959Y from Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement of Vehicle SMF 4959Y.
- c) Police Report of Vehicle SMF 4959Y.
- d) Final Repair Bill of SMF 4959Y from M/s Apex Motoring.
- e) Colour damaged vehicle photographs of SMF 4959Y.

Pre-Repair Inspection Date: 14/07/2022 at M/s 365 Automotive Pte Ltd, 25 Kaki Bukit Road 4 #01-55 Synergy @KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMF 4959Y

Make & Model : Toyota Prius Hybrid 1.8S Cvt

Year of Registration : 2018

Chassis Number : ZVW506144369

Engine Capacity : 1797 cc

- 2. We recommend that the repairs of the entire damage require about <u>11 (Eleven)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.