

ASS. REC. BY: Tau J M

REP:

INC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / NS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: Awang Vehicle: IN / OUT

Veh No: SHA 1213X Yr Regn: 20/9 May
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 386197 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JAPKBSFY80308161
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 145/65R15
 R: 7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wan H He
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 6/10/22
 Survey held at Comfort Lodge
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?
 2) _____

Rep. Format: _____
 Lump Sum / L.B.K. ()

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHA1213X
 Make : TOYOTA
 Model : PRIUS
 DOA : 06.10.2022

Date : 06.10.2022
 Insurance: INCOME
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
1	REAR TRUNK LID LOGO (PRIUS)			\$52.90
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$60.80
1	REAR BUMPER			\$503.04
1	REAR BUMPER UNDER COVER			\$654.96
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$378.32
1	REAR BUMPER UNDER SIDE COVER LH			\$223.00
1	REAR BUMPER TOWING COVER			\$82.70
1	TAIL LAMP LH UPPER			\$557.90
1	TAIL LAMP LH LOWER			\$570.00
	SUB TOTAL			\$4,273.12
	LESS 25%			\$1,068.28
	DISCOUNTED TOTAL			\$3,204.84
1	REAR TRUNK LID APPS STICKER			\$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				\$262.00
	Labour Charge			
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$60.00
	Tuff Kote			\$60.00
	Remove/Refix Reverse Sensor			\$60.00
	TOTAL LABOUR			\$1,830.00
	ESTIMATE TOTAL			\$5,296.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Date:

Tan Kah 97495749
 WP 610/12 C 430 pc
 1/3 Resurvey after repair
 Tan Kah C. Whantown 2 day

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 06.10.2022 11:06

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC N05532250

CUSTOMER MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) COUNT CARD NO.	REGN NO: SHA1213X	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)06.10.2022 11:03	DATE/TIME IN
	YR OF MANU. 02.05.2019	TARGET DATE
	CHASSIS CODE JTDKB3FU803080161	COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 06.10.2022
TURE: 3P 06.10.2022

NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHA1213X

CHIANG

Vehicle No.:

SHA1213X

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard