

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159334
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/3

Company
MS
FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
HARVINDER
SINGH S/O BALJIT
796 WOODLANDS DRIVE 72
#13-39
Singapore 730796

Document no.
Document date 06-10-2022
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2022029357/ 1
Job order date 06-10-2022
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SLC3335G	BQ13HZ	14-11-2018	WVVZZZAUZKW015563	Golf Comfortline 1.4 I TSI 92kW DSG	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00 ✓	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00 ✓	513.60
5G6807417BQGRU	Cover For Bumper Primed	1	pcs.	1,382.73	#1	1,382.73 ✓	1,479.52
5G6807441A GRU	Cover For Towing Eye Prim	1	pcs.	33.66	#1	33.66 ✓	36.02
5G6807393	Guide Piece	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807394	LHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807394	Guide Piece	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807393A	RHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807393A	Guide Piece	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807394A	LHR BUMPER BRACKET (OUTER)	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807394A	Guide Piece	1	pcs.	41.89	NN #1	X 41.89	44.82
5G6807863C	RHR BUMPER BRACKET (OUTER)	1	pcs.	70.74	NN #1	X 70.74	75.69
5G6807863C	Attachment Strip	1	pcs.	70.74	NN #1	X 70.74	75.69
5G6807863C	RR BUMPER BRACKET (CENTER)	1	pcs.	70.74	NN #1	X 70.74	75.69
5Q0919275B GRU	Sensor Primed	1	pcs.	190.18	NN #1	X 190.18	203.49
5Q0919133 9B9	Seal Ring Satin Black	4	pcs.	1.46	#1	5.84 ✓	6.25
5G0919491D	Sensor Bracket	2	pcs.	13.60	#1	27.20 ✓	29.10
5G0919492D	Sensor Bracket	1	pcs.	14.19	#1	14.19 ✓	15.18
5G0919491E	Sensor Bracket	1	pcs.	13.60	#1	13.60 ✓	14.55
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94 ✓	91.96
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85 ✓	73.67
5G0807305D	Bumper	1	pcs.	732.39	NN #1	X 732.39	783.66
N 0385494	Rivet	4	pcs.	0.44	#1	1.76 ✓	1.88
5G6807568R 9B9	Rear Diffusor Satin Black	1	pcs.	349.21	NN #1	X 349.21	373.65
5G6853333 2ZZ	Decorative Moulding Brigh	1	pcs.	159.63	NN #1	X 159.63	170.80
5G6853333 2ZZ	REAR BUMPER LOWER CHROME MOLDING (CENTER)	1	pcs.	131.29	NN #1	X 131.29	140.48
5G6853331A 2ZZ	Decorative Moulding Brigh	1	pcs.	131.29	NN #1	X 131.29	140.48
5G6853332A 2ZZ	LHR BUMPER CHROME MOLDING	1	pcs.	131.29	NN #1	X 131.29	140.48
5G6853332A 2ZZ	Decorative Moulding Brigh	1	pcs.	131.29	NN #1	X 131.29	140.48
5G6853332A 2ZZ	RHR BUMPER CHROME MOLDING	1	pcs.	131.29	NN #1	X 131.29	140.48
5G0945105C	Reflector LH	1	pcs.	79.04	#1	79.04	84.57
5G0945106C	Reflector RH	1	pcs.	79.04	#1	79.04	84.57
5G6827025Q	Rear Trunk Lid	1	pcs.	3,107.80	#1	3,107.80 ✓	3,325.35
5G6827705E	Gasket	1	pcs.	289.35	#1	289.35 ✓	309.60
510827861A	BOOT LID SEAL	1	pcs.	9.03	#1	9.03 ✓	9.66
5G6827505B 9B9	Water Drain Hose	1	pcs.	9.03	#1	9.03 ✓	9.66
5G6827505B 9B9	Hood Latch Satin Black	1	pcs.	332.14	#1	332.14 ✓	355.39
5G0827517E	LID LOCK	1	pcs.	59.94	#1	59.94	64.14
5G0853617A	Striker Plate	1	pcs.	59.94	#1	59.94	64.14
5G0853617A	Vw Sign	1	pcs.	101.88	#1	101.88	109.01

VOLKSWAGEN CENTRE SINGAPORE

Alexandra Road
Singapore 159934
Reg. No.: 199101494Z
ST No.: M200985052



Quotation
Non binding - Preview

Page 2/3

Company
MS
FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
HARVINDER
SINGH S/O BALJIT
796 WOODLANDS DRIVE 72
#13-39
Singapore 730796

Document no.
Document date 06-10-2022
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2022029357/ 1
Job order date 06-10-2022
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage		
SLC3335G	BQ13HZ	14-11-2018	WWWZZZAUZKW015563	Golf Comfortline 1.4 TSI 92kW DSG	20		
Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
					#1	86.75	92.82
5G0853687 2ZZ	Inscription Bright Chrome GOLF WORDING	1	pcs.	86.75	#1	86.75	92.82
5G0945087B	Additional Brake Light Wi	1	pcs. (ph)	183.08	#1	183.08	195.90
D 002000A2	Adhesive Remover	1	pcs.	120.29	#1	120.29	128.71
D 00920002	Primer	1	pcs.	30.27	#1	30.27	32.39
D 00950025	Applicator	1	pcs.	11.16	#1	22.32	23.88
D 181802M1	Activator	2	pcs.	26.27	#1	26.27	28.11
D 169300M2	1k Window Adhesive	1	pcs.	51.44	#1	102.88	110.08
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	LABOUR	83	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINTING	1	pcs.	800.00	#1	3,200.00	3,424.00
	R&R REAR WINDSCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRASFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	MS FIRST CAPITAL DIRECT DOA: 4/10/2022 TP VEH NO: SHB690C SURVEY BY:						

Quotation valid till 13-10-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	18,346.14	7%	1,337.43	19,106.14	20,443.57
Total	760.00	18,346.14		1,337.43	19,106.14	20,443.57

Steve (LKK)
10/10/22, 10.30

Mr N
P/P
by Bk y

Chris

Service Advisor

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts and resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

7 to 10 days

Acknowledged by Repairer

Signature:

Date: