



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009921/Acy3e2	
			Date: 10/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMJ 4540A	Veh. Inspected	PC 8414G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203623/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	07/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE COMMUTER	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GDH2232001840	Colour	WHITE
	Odometer	262882 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	6 mm
	L/H Front Tyre	195 R15C	MICHELIN	6 mm
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/10/2022	Inspection Date	07/10/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	