

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	949B
Vehicle Details	
Vehicle No.:	PC8414G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1GD8423235
Chassis No.:	GDH2232001840
Maximum Power Output:	-
Open Market Value:	\$45,604.00
Original Registration Date:	19 Jun 2019
First Registration Date:	19 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$2,281.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,318.00
COE Rebate Amount:	\$17,596.00
Total Rebate Amount:	\$17,596.00

The information contained herein is correct as at 11 Oct 2022

OK

This is DBS digibanking



I've got the scoop on reliable, timely financing for business growth!



Hiace Commuter 2.8A GL

Price Range

Depreciation

2019

Vehicle Type



Search




Advanced Search

Used Car Comparison

--- Comparing 2 Vehicles ---

Toyota Hiace Commuter 2.8A GL

Toyota Hiace Commuter 2.8A GL



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

Back to search result

CAR DETAILS

Price	\$106,000	\$107,800	-	-
Instalment	N.A.	N.A.	-	-
Registration Date	10-Oct-2019	18-Nov-2019	-	-
Manufactured	2019	2019	-	-
Mileage	155,000 km	-	-	-
Transmission	Auto	Auto	-	-
Engine Cap	2,754 cc	2,754 cc	-	-
Road Tax	-	-	-	-
Power	-	-	-	-
Curb Weight	2,180 kg	2,180 kg	-	-
Features	-	-	-	-
Accessories	-	-	-	-
Description	1 owner, well maintained. New tyres. Not in hurry to sell.	Consignment unit. Euro 6 excursion bus. In great condition and well taken care by owner. Comes with original stock. Contact me to arrange for viewing and test drive appointment.	-	-
COE	\$27,800	\$22,252	-	-
OMV	\$46,713	\$48,455	-	-
ARF	\$2,336	\$2,423	-	-
Depreciation	\$15,140 /yr	\$15,170 /yr	-	-
No. of Owners	1	1	-	-
Type of Vehicle	Bus	Bus	-	-
Category	Direct Owner Sale	-	-	-
Availability	Available	Available	-	-
Remarks	Fuel type Diesel	Fuel type Diesel	-	-

SELLER INFORMATION

Seller	Direct Owner	Swee Seng Motors	-	-
Address	-	21 Toh Guan Road East #01-01/02	-	-


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 07.10.2022

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **PC8414G**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 06.10.2022
TIME OF ACCIDENT : 19:40 HOURS

GDH2232001840

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,054.20	\$ 2,054.20
2	TAILGATE DETECTOR <i>and</i>	1	\$ 289.40	\$ 289.40
3	TAILGATE DETECTOR WIRE HARNESS <i>for</i>	1	\$ 286.30	\$ 286.30
4	TAILGATE DETECTOR WIRE HOLDER <i>for</i>	1	\$ 98.20	\$ 98.20
5	TAILGATE LOGO <i>?</i>	1	\$ 75.10	\$ 75.10
6	TAILGATE 'HIACE' EMBLEM <i>for</i>	1	\$ 57.40	\$ 57.40
7	TAILGATE 'GL' EMBLEM <i>for</i>	1	\$ 52.70	\$ 52.70
8	TAILGATE INNER BOARD (LOWER) <i>Rehd</i>	1	\$ 271.80	\$ 271.80
9	TAILGATE WEATHERSTRIP <i>at</i>	1	\$ 329.60	\$ 329.60
10	TAILGATE REVERSE CAMERA <i>new</i>	1	\$ 1,135.20	\$ 1,135.20
11	TAILGATE INNER LOCK <i>Jammed</i>	1	\$ 475.60	\$ 475.60
12	TAILGATE LOWER LOCK <i>new</i>	1	\$ 105.00	\$ 105.00
13	TAILGATE CENTER LOCK MOTOR <i>new</i>	1	\$ 435.70	\$ 435.70
14	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
15	TAIL LAMP <i>at</i>	2	\$ 374.60	\$ 749.20
16	TAILLAMP LOWER GARNISH <i>and</i>	2	\$ 110.10	\$ 220.20
17	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
18	REAR BUMPER <i>Rehd</i>	1	\$ 395.00	\$ 395.00
19	REAR BUMPER BRACKET <i>Best</i>	4	\$ 85.40	\$ 341.60
20	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
21	REAR END PANEL (INNER) <i>Dented</i>	1	\$ 1,043.20	\$ 1,043.20
22	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 542.10	\$ 542.10
23	REAR FLOOR PANEL <i>Repair</i>	2	\$ 324.20	\$ 648.40
24	REAR FLOOR PANEL MAT <i>new</i>	1	\$ 1,591.50	\$ 1,591.50
25	REAR SPARE TYRE HOLDER BRACKET <i>Best</i>	1	\$ 649.30	\$ 649.30
26	REAR SPARE TYRE HOLDER BOLT <i>new</i>	1	\$ 60.00	\$ 60.00

642730
482047

TOTAL PRICE \$ 12,174.70
LESS 25% \$ 3,043.68
SUB TOTAL PRICE \$ 9,131.03

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC8414G**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 06.10.2022
 TIME OF ACCIDENT : 19:40 HOURS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
4	TAILGATE WEATHERSTRIP PROTECTOR COVER (SPECIAL TYPE) <i>Defect</i>	1	\$ 400.00	\$ 400.00
5	TAILGATE CENTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	TAILGATE STICKER 'EMERGENCY DOOR' <i>new</i>	1	\$ 40.00	\$ 40.00
8	TAILGATE STICKER 'PULL TO OPEN' <i>new</i>	1	\$ 80.00	\$ 80.00
9	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00
10	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
12	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
13	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
14	REAR END PANEL (INNER) SEALANT <i>2 new</i>	1	\$ 150.00	\$ 150.00
15	REAR END PANEL (OUTER) SEALANT	1	\$ 150.00	\$ 150.00
16	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
17	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>new</i>	1	\$ 1,800.00	\$ 1,800.00
18	REAR FLOOR PANEL MAT CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 3,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,800.00	1000
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	900.
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
5	TRANSFER TAILGATE MECHAISM	\$ 80.00	✓
6	<i>To spray tuff coat.</i>	\$ 120.00	80.
7	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
8	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC8414G**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 06.10.2022
 TIME OF ACCIDENT : 19:40 HOURS

9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

TOTAL \$ 5,240.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,681.03
 TOTAL LABOUR COST : \$ 5,240.00
 TOTAL REPAIR COST : \$ 17,921.03

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lj
 2/5 07/10/22
 06 Days

total: 7575 47
 1/5: 6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: