



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22004010/Rqy3e2-1	
			Date: 08/03/2023	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 3129M	Veh. Inspected	SLE 6056G	
Policy No.	Z/21/VC06/112962	Coverage (\$)	0.00	
Claim No.	21/22/22/VC06/025729	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	06/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE 1.5G CVT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GK81004867	Colour	WHITE	
Odometer	145969 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	MICHELIN	6 mm	
L/H Front Tyre	195/55 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/04/2022	Inspection Date	28/04/2022	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	