

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybjt@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Goh Sook Beng
Block 319 Hougang Avenue 5 #02-21
Singapore 530319

Our Ref : PA/AZ5555/0322/tpw
Date : 12 July 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 14 March 2022
Vehicle No	: AZ 5555 J	Date of Assignment	: 16 March 2022
Make	: Honda	Date of Inspection	: 16 March 2022
Model	: ADV750	Date of Re-inspection	: 22 March & 07 July 2022
Registration Date	: 22 November 2021	COE Expiry	: 21 November 2031
Color	: Red	Chassis No	: JH2RH10A1MK013551
Odometer	: 9,640km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Bridgestone	120/70-17	6mm
Rear	Bridgestone	160/60-15	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and right sides.
Please refer to photographs and assessment of repairs for details
Enclosed (64) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$22,305.65 Revised Assessment : \$19,200.00 Lump sum

Survey conducted at Ong Motor Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Eight (8) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note: The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICESVehicle No: **AZ 5555 J**

Our Ref: PA/AZ5555/0322/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Windscreen ✓	1 pc	Grazed	587.60	587.60
2	Windscreen holder ✓	1 pc	Cracked	205.30	205.30
3	Windscreen adjust link ✓	1 pc	Bent	560.50	560.50
4	Handle bar ✓	1 pc	Bent	520.60	520.60
5	Handle switch winker & hone ✓	1 pc	Cracked	752.60	752.60
6	Handle bar guard knuckle ✓	1 set	Cut/cracked	345.80	345.80
7	Side mirror ✓	1 set	Cut/grazed	380.00	380.00
8	Brake lever RH ✓	1 pc	Broken	129.50	129.50
9	Brake lever LH ✓	1 pc	Bent	129.50	129.50
10	Front winker light (LED) @ \$126/-	2 pcs	Serviceable	252.00	~
11	Headlamp assy (LED) ✓	1 pc	Cracked	3,816.40	3,816.40
12	Cowling & headlamp stay complete ✓	1 set	Distorted	841.50	841.50
13	Nose cover (mat black) ✓	1 pc	Cracked	280.50	280.50
14	Front panel upper cover (mat black) ✓	1 pc	Cracked	362.40	362.40
15	Front upper inner cover (Black) ✓	1 pc	Cut	220.30	220.30
16	Front nose cover ✓	1 pc	Cracked	330.20	330.20
17	Front fork assy @ \$2178.60/- X SVC	2 pcs	Bent	4,357.20	4,357.20 X
18	Steering stem X SVC	1 pc	Distorted	831.70	831.70 X
19	Front fender ✓	1 pc	Cracked	383.60	383.60
20	Front wheel rim assy X SVC	1 pc	Warped	1,085.00	1,085.00 X
21	Front side outer cowling @ \$895.40/- ✓	2 pcs	Cracked/torn	1,790.80	1,790.80
22	Front side cowling under cover @ \$160.30/- ✓	2 pcs	Cracked/deformed	320.60	320.60
23	Air duct @ \$149.80/- X SVC	2 pcs	Hdr cracked	299.60	299.60 X
24	Floor step panel @ \$417.80/- ✓	1-2 pcs	Cut LH	835.60	417.80
25	Floor step lower skirt cover @ \$455.40/- ✓	2 pcs	Cut/grazed	910.80	910.80
26	Exhaust muffler X REPAIR	1 pc	Dented/cut	1,996.40	1,996.40 X
27	Muffler protector cover ✓	1 pc	Dented	182.50	182.50
				22,708.50	22,038.70
List price less 10% discount				2,270.85	2,203.87
				20,437.65	19,834.83
					13468.8
					12121.92
<u>Add special nett item</u>					
28	Front number plate (sticker) ✓	1 pc	Necessary	18.00	15.00
29	Steering cone & bearing X SVC	1 set	Necessary	250.00	225.00
				268.00	240.00

PRUDENT ADJUSTORS SERVICES

Vehicle No: AZ 5555 J

Our Ref: PA/AZ5555/0322/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Labour charges

Towing (2 trips)	150.00	120.00	50
Body frame align	650.00	550.00	×
Remove & replace damage parts	800.00	600.00	300
	1,600.00	1,270.00	

Total parts & labour concluded	<u>22,305.65</u>	<u>21,344.83</u>
--------------------------------	------------------	------------------


Lump sum repair adjustment (less 10% due to no used parts)	<u>19,200.00</u>
--	------------------

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.

12486.92

-20%: 10k

4 Days


Prudent Adjustors Services
Bok Jee Tan