



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0863/2022/EQ
DATE : 7-Oct-22
WIP : 45065

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SMY 9046 Z**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MR NG DILLON
ADDRESS : BLK 140 LORONG AH SOO
#12-203
SINGAPORE 530140
TELEPHONE : HP +65 98629654
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210156113
VEHICLE NO : **SMD 6446 H**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 31/12/2021
ENGINE NO : DEM 033948
CHASSIS NO : WAUZZZF50MA059857
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Oct-22
PLACE OF ACCIDENT : CATHOLIC HIGH SCHOOL (PRIMARY)
CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 6446 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	
3	TO RESPRAY FRONT BUMPER.	\$ 1,200.00	
4	TO REAPPLY PAINT COATING FOR THE AFFECTED PANELS. (BY OWNER)	S/N \$ 100.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,172.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 6446 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	
2	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	RADIATOR AIR GUIDE - LH / RH	2	\$ 144.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	
9	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH	2	\$ 108.00	
10	RADIATOR GRILLE TRIM - CENTER	1	\$ 127.00	
11	RADIATOR GRILLE	1	\$ 1,881.00	
12	RADIATOR GRILLE COVER	1	\$ 141.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
15	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	
16	FRONT BUMPER TOP COVER	1	\$ 143.00	
17	CAUTION SIGN STICKER	1	\$ 16.00	
18	AIR CONDITONER STICKER	1	\$ 9.00	
19	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	
20	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
SUB TOTAL SPARE PARTS		:	\$ 8,209.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 6446 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER	2	\$ 531.00	
22	PARKING PARKING AID SEAL RING	4	\$ 10.00	
23	NOISE INSULATION	1	\$ 640.00	
24	FRONT NO PLATE	S/N	\$ 60.00	
25	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 9,850.00	
TOTAL LABOUR CHARGES		:	\$ 3,172.00	
GRAND TOTAL		:	\$ 13,022.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

REVOL

Carz Makeover Pte Ltd

Blk 10, Ang Mo Kio Industrial Park 2A AMK Autopoint #01-12 (S) 568047 Tel:6746 6281

Quotation

ATTN : MR NG DILLON
Contact : 98629654
Fax : -

Our Ref : R22-1006
Page : 1 OF 1

Thank you for requesting this Quotation. We look forward to your reply and to serve you in our best upon confirmation.

Date	DESCRIPTION	Unit Cost	QTY	AMT <u>SGD</u>
6/10/2022	For SMD6446H AUDI A5 SPORTBACK 2.0 TFSI S TRONIC (110 KW) 1. Recoating of Zetough Titanium Paint Protection Coating on Front Bumper			\$ 100.00
			Total	\$ 100.00

Validity : 01 MONTH FROM THE DATE OF QUOTATION

For Revol Carz Makeover Pte Ltd

Marcus

Marcus Koh
Manager

Confirmation order

Sign and company stamp



Revol Carz Makeover Pte Ltd
10 Ang Mo Kio Industrial Park 2A #01-12
AMK Autopoint S568047
Tel: 67466281
Website: www.revol.com.sg
Email: enquiry@revol.com.sg

Invoice No:
2022/03/0680201

Name:	DILLON NG
Address:	CONFIDENTIAL
Tel:	CONFIDENTIAL
Email:	CONFIDENTIAL

Car Make Model:	AUDI A5 SPORTBACK 2.0 TFSI S TRONIC (110 KW)
Car Plate No:	SMD6446H

Date: 12 Mar 2022

Description	Amount
ZeTough Titanium Foundation balance 2 mainteance convert over	\$988.00
Total Amount:	\$988.00

Our In House Services

- Paint Protection & Grooming
- Third Party Insurance Claims
- Paintless Dent Removal

- Car Servicing & Repair
- Panel Beating & Respray Works
- Vehicle De-registration

Mode of Payment: **UOB MASTER / VISA**

cheque payment, please make payable to:
Revol Carz Makeover Pte Ltd

Now payment, our PayNow ID is
373MRRR

Marcus Koh (93222318)

Terms and conditions:

- All Revol Carz Makeover Pte Ltd Services are strictly by appointment basis only.
- Revol Carz Makeover Pte Ltd management reserves the right to amend the terms and conditions without prior notice.

NG's signature