



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1061C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (WCP)	BUCKLED	683.42	683.42
1	WICK, BUMPER, FR (WCP)	SERVICEABLE	69.30	-
1	HEADLAMP RH (WCP)	MTG BROKEN	419.45	419.45
1	FRONT FENDER RH (WCP)	BUCKLED	265.14	265.14
1	HEADLAMP LOWER BEAM RH (WCP)	TO REPAIR SEE LABOUR	75.60	-
1	RADIATOR GRILLE (WCP)	SERVICEABLE	76.20	-
1	BUMPER SIDE BRACKET RH (WCP)	DISTORTED	25.23	25.23
1	BUMPER SIDE BRACKET LH (WCP)	SERVICEABLE	25.23	-
1	CROSSRAIL , BUMPER FR (WCP)	SERVICEABLE	357.19	-
1	BONNET HINGE RH (WCP)	TO REPAIR SEE LABOUR	69.50	-
1	BONNET HINGE LH (WCP)	TO REPAIR SEE LABOUR	68.18	-
1	CLAMPING KIT BUMPER FR (WCP)	NECESSARY	34.62	34.62
1	BUMPER TOP GRILLE (WCP)	SERVICEABLE	323.29	-
1	BUMPER FRT (WCP)	BUCKLED/ CRACKED	756.25	756.25
1	ORNAMENT,GRILLE (WCP)	MISSING	118.06	118.06
	COST PLUS 10%		336.67	230.22
			3,703.33	2,532.39
<u>LABOUR</u>				
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF HEADLAMP LOWER BEAM RH, BONNET HINGE RH AND BONNET HINGE LH.		720.00	400.00
	TO PUTTY & RESPRAY ON FRONT BUMPER, BONNET, RHF FENDER RHF DOOR AND AFFECTED AREA.		1,200.00	600.00
	TO CHECK WIRING, FOCUS HEADLAMP.		100.00	20.00
	TO REMOVE STICKER AND REPLACE ADVERTISEMENT STICKER.		550.00	550.00
			2,570.00	1,570.00
GRAND TOTAL			6,273.33	4,102.39



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
LESS EXCESS			-1,500.00
NETT LIABILITY			1,700.00

Report Ref No. CS/AWA22009936/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.