

7/10/2022



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OD

Ins Company : ALLIED WORLD

Excess : _____

Date of Accident : 23.09.2022

Suggested Days of Repair : _____

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,366.66

Plus/Less 10% \$ 336.67

Total of Cost / List \$ 3,703.33

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 3,703.33

Labour (Appendix B) \$ 2,020.00

Total Repair Cost \$ 5,723.33

The above total will be subjected to 7% G.S.T.

Vehicle No. : GBC1061C

Make & Model : FIAT / DOBLO CARGO 1.3MJ

Year of Manufacture : 2011

Chassis No. : ZFA269300009097831

Engine No. : 199A30004067319

Policy No. : _____

Time of Accident : 1255

In-house Vehicle Assessor

Case Owner : Johari BH

Signature : _____

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

*NOT Authorized
L/Rup @
Permy After Pain
Ex @1500*

Name of Surveyor : Kenneth
Company : UKIC
Survey conducted on : 10/10/22 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~not~~ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 10/10/22

Spare Parts

Vehicle No : GBC1061C Case Owner : Johari BH
 Make & Model : FIAT / DOBLO CARGO 1.3M. Year Manufacture : _____
 Chassis No : ZFA269300009097831 Engine No : 199A30004067319
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	BONNET <i>Bu</i>	1	\$ 683.42				✓
2	WICK, BUMPER, FR	1	\$ 69.30				✓
3	HEADLAMP RH <i>My Bu</i>	1	\$ 419.45				✓
4	FRONT FENDER RH <i>Bu</i>	1	\$ 265.14				✓
5	HEADLAMP LOWER BEAM RH	1	\$ 75.60				✓
6	RADIATOR GRILLE <i>Pin</i>	1	\$ 76.20				X
7	BUMPER SIDE BRACKET RH <i>Di't</i>	1	\$ 25.23				✓
8	BUMPER SIDE BRACKET LH <i>Pin</i>	1	\$ 25.23				X
9	CROSSRAIL, BUMPER FR	1	\$ 357.19				✓
10	BONNET HINGE RH	1	\$ 69.50				✓
11	BONNET HINGE LH	1	\$ 68.18				✓
12	CLAMPING KIT BUMPER FR <i>Mc</i>	1	\$ 34.62				✓
13	BUMPER TOP GRILLE <i>Pin</i>	1	\$ 323.29				X
14	BUMPER FRT <i>Bu/CM</i>	1	\$ 756.25				✓
15	ORNAMENT,GRILLE <i>MS</i>	1	\$ 118.06				✓
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

