

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0865/2022/EQ
DATE : 8-Oct-22
WIP : 45240

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/2022

YOUR INSURED VEH NO : SNE 7090 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR GUO QIANLI
ADDRESS : 123 MEYER ROAD
#23-06
SINGAPORE 437934
TELEPHONE : HP +65 97649502
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : C0129678
VEHICLE NO : **SNF 6142 L**
MODEL CODE : AUDI Q3 2.0 TFSI QU S-TRONIC
MODEL YEAR : 10/6/2022
ENGINE NO : DNN 070415
CHASSIS NO : WAUZZZF36N1095066
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Oct-22
PLACE OF ACCIDENT : GRANGE ROAD BETWEEN SOMERSET ROAD
AND DEVONSHIRE ROAD MID LANE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 6142 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
3	TO RESPRAY REAR BUMPER.	\$	1,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 6142 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,958.00	
2	REAR BUMPER SPOILER	1	\$ 510.00	
3	REAR BUMPER TOW EYE COVER	1	\$ 48.00	
4	REAR BUMPER BRACKET	1	\$ 53.00	
5	REAR BUMPER REFLECTOR - RH	1	\$ 46.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 693.00	
7	REAR BUMPER GUIDE SECTION - RH	1	\$ 71.00	
8	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 120.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
10	REAR PARKING AID SEAL RING	4	\$ 10.00	
11	REAR WHEEL COVER - LH / RH	2	\$ 566.00	
12	REAR VENT TRIM	1	\$ 79.00	
13	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 4,985.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 7,737.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT