



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SNA1900A
Date of Accident : 06 October 2022

Messrs KCT Bus Service

Date : 07 October 2022

Estimate To Repair PZ1473K - Golden Dragon XML6770J18
Chassis No : LL3ADADE8FA002062

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front body panel <i>body</i>	\$ 1,800.00
02	1 pc	front windscreen rubber <i>11</i>	\$ 600.00 <i>X</i>
03	1 pc	n/s headlamp <i>one</i>	\$ 850.00
04	1 pc	front bumper <i>one</i>	\$ 1,280.00 <i>1020</i>
05	1 pc	front bumper fog lamp n/s <i>one</i>	\$ 280.00 <i>220</i>
06	1 pc	front center grille <i>11</i>	\$ 480.00 <i>X</i>
		Less 10 % <i>for minor sanding</i>	\$ 5,290.00
			\$ 529.00
			\$ 4,761.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 400.00 <i>200</i>
02		To remove and refit front windscreen glass.	\$ 180.00 <i>100</i>
03		To rust-proofing of the affected areas.	\$ 150.00 <i>30</i>
04		To check electrical lighting concerned.	\$ 150.00 <i>20</i>
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00 <i>1000</i>
06		Putty and spray painting of the affected portion.	\$ 900.00 <i>600</i>
			\$ 2,980.00
		Total	\$ 7,741.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Allowed
LKK works
7/10/22
L/S \$ 4300
4 days
When phd. After MP

P- 3890
102
3501
5457
22
4360