

ASS. REC. BY:

REF:

AG/220009946/kp

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

872K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX1217S

Yr Regn:

03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mazda 3

c.c

1496

Colour

M.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

61252

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TM6BN22A8J0-183141

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/TOYO/YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

8/10/22

D.O.I.

17/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear AIS & 131

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/11/21 Rpt @ 21550t Control

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLX1217S
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Not Authorized

WS Ref: TP/AIG

1/Rep 8

Claim Type: Third Party

Recovery After Repair

Accident Date: 06/10/2022

TP Veh Reg No: GBL9899C

21 days

Estimate No: ES2291063/YISHUN

Date: 17 Oct 2022

Policy No: 5130022771

Veh Reg No: SLX1217S

Make/Model: MAZDA MAZDA 3
SEDAN 1.5 AT LED EU6

Chassis No: JM6BN22A8J0183141

Engine No: P520472853

Reg. Date: 16/03/2018

Estimate Repair Cost to Vehicle No :SLX1217S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	856.80	1 PC	<i>Br</i> 856.80	✓
2 FRONT BUMPER LH DAY RUNNING LAMP	147.00	1 PC	<i>Sn</i> 147.00	X
3 FRONT BUMPER DAY RUNNING LAMP CHROME	71.30	1 PC	<i>Sn</i> 71.30	X
4 FRONT BUMPER REINFORCEMENT	502.80	1 PC	<i>Br</i> 502.80	✓
5 FRONT BUMPER REINFORCEMENT COVER	97.40	1 PC	<i>Sn</i> 97.40	X
6 FRONT BUMPER REINFORCEMENT SPONGE	116.20	1 PC	<i>Sn</i> 116.20	X
7 FRONT GRILLE BASE	135.50	1 PC	<i>CM</i> 135.50	✓
8 FRONT GRILLE CENTRE EMBLEM	61.50	1 PC	<i>Del</i> 61.50	✓
9 FRT GRILLE FIN - RH TOP	39.10	1 PC	<i>mi</i> 39.10	✓
10 FRONT GRILLE FIN - LH TOP	39.10	1 PC	<i>CM</i> 39.10	✓
11 FRONT GRILLE FIN - RH MID 2	39.10	1 PC	<i>mi</i> 39.10	✓
12 FRONT GRILLE FIN - LH MID 2	39.10	1 PC	<i>CM</i> 39.10	✓
13 FRONT GRILLE FIN - RH MID 3	39.10	1 PC	<i>Del</i> 39.10	X
14 FRONT GRILLE FIN - LH MID 3	39.10	1 PC	<i>Del</i> 39.10	X
15 FRONT GRILLE LOWER FIN	71.00	1 PC	<i>Sn</i> 71.00	X
16 FRONT GRILLE MID FIN	71.00	1 PC	<i>Sn</i> 71.00	X
17 FRONT GRILLE BOTTOM FIN	59.70	1 PC	<i>Sn</i> 59.70	X
18 FRONT GRILLE LH SURROUND	20.50	1 PC	<i>CM</i> 20.50	✓
19 FRONT GRILLE LH SURROUND CHROME	191.70	1 PC	<i>CM</i> 191.70	✓
20 FRONT GRILLE RH SURROUND	20.50	1 PC	<i>Sn</i> 20.50	X
21 FRONT GRILLE RH SURROUND CHROME	191.70	1 PC	<i>Sn</i> 191.70	X
22 FRONT NUMBER PLATE GARNISH	74.60	1 PC	<i>Del</i> 74.60	✓
23 FRONT GRILLE LH BRACKET	27.30	1 PC	<i>Sn</i> 27.30	X
24 FRONT GRILLE LH BRACKET PIN	5.50	1 PC	<i>Sn</i> 5.50	X
25 FRONT GRILLE LH BRACKET PIN HOLDER	12.00	1 PC	<i>Sn</i> 12.00	X
26 FRONT GRILLE RH BRACKET	27.30	1 PC	<i>Sn</i> 27.30	X
27 FRONT GRILLE RH BRACKET PIN	5.50	1 PC	<i>Sn</i> 5.50	X
28 FRONT GRILLE RH BRACKET PIN HOLDER	12.00	1 PC	<i>Sn</i> 12.00	X
29 FRONT GRILLE TOP PLATE	141.40	1 PC	<i>CM</i> 141.40	✓
30 FRONT GRILLE TOP PLATE CLIPS	4.50	10 PCS	<i>Sn</i> 45.00	✓
31 FRONT GRILLE TOP PLATE RIVETS	5.50	6 PCS	<i>Sn</i> 33.00	✓
32 FRONT GRILLE TOP PLATE COVER	355.50	1 PC	<i>CM</i> 355.50	✓
33 FRONT GRILLE TOP PLATE COVER CLIPS	4.50	6 PCS	<i>Sn</i> 27.00	✓
34 FRONT BUMPER LOWER STIFFENER	144.60	1 PC	<i>Sn</i> 144.60	X
35 HEADLAMP LH <i>3778.60</i>	3,778.60	1 PC	<i>Br</i> 3,778.60	✓
36 HEADLAMP LOWER BEAM LH	12.90	1 PC	<i>Sn</i> 12.90	X
37 HEADLAMP RH <i>3778.60</i>	3,778.60	1 PC	<i>mi</i> 3,778.60	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 06/10/2022

TP Veh Reg No: GBL9899C

Estimate No: ES2291063/YISHUN

Date: 17 Oct 2022

Policy No: 5130022771

Veh Reg No: SLX1217S

Make/Model: MAZDA MAZDA 3
SEDAN 1.5 AT LED EU6

Chassis No: JM6BN22A8J0183141

Engine No: P520472853

Reg. Date: 16/03/2018

Estimate Repair Cost to Vehicle No :SLX1217S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
38 HEADLAMP LOWER BEAM RH	12.90	1 PC	12.90	X
39 FRT SUPPORT PANEL	491.20	1 PC	491.20	✓
40 FRONT LH FENDER INNER PANEL	576.80	1 PC	576.80	X
41 FRONT LH FENDER	350.60	1 PC	350.60	✓
42 BONNET <i>1126.70</i>	1,126.70	1 PC	1,126.70	✓
43 BONNET RUBBER SEAL - FRONT	66.80	1 PC	66.80	✓
44 BONNET RUBBER SEAL - MID	92.00	1 PC	92.00	✓
45 BONNET HINGES	43.10	2 PCS	86.20	✓
46 BONNET LOCK	207.10	1 PC	207.10	✓
47 AIR-CON CONDENSER <i>1116.20</i>	1,116.20	1 PC	1,116.20	✓
48 RADIATOR	1,118.30	1 PC	1,118.30	✓
49 RADIATOR TOP HOSE	62.50	1 PC	62.50	X
50 RADIATOR TOP MOUNTINGS	38.00	2 PCS	76.00	X
51 RADIATOR FAN ASSY <i>1424.70</i>	1,424.70	1 PC	1,424.70	✓
52 AIR INTAKE DUCT	97.40	1 PC	97.40	✓
53 AIR FILTER TOP CASING	79.20	1 PC	79.20	✓
54 AIR FILTER LOWER CASING	83.70	1 PC	83.70	✓
55 AIR RESONATOR	274.40	1 PC	274.40	✓
56 AIR RESONATOR DUCT	89.10	1 PC	89.10	X
57 THROTTLE VALVE AIR DUCT	102.20	1 PC	102.20	X
58 WIPER GARNISH LH COVER	227.40	1 PC	227.40	X
59 REAR BUMPER <i>R</i>	996.70	1 PC	996.70	✓
60 REAR BUMPER LH RETAINER	53.00	1 PC	53.00	✓
61 REAR BUMPER LH REFLECTOR	53.00	1 PC	53.00	✓
62 REAR BUMPER LH TOW-EYE COVER	19.50	1 PC	19.50	✓
63 REAR BUMPER REINFORCEMENT	564.20	1 PC	564.20	✓
64 REAR BUMPER PDC SENSORS	203.00	2 PCS	406.00	✓
65 REAR BUMPER PDC SENSOR HOLDERS <i>S</i>	16.00	4 PCS	64.00	X
66 REAR BUMPER PDC WIRE HARNESS <i>S</i>	152.80	1 PC	152.80	X
67 BOOTLID	1,005.30	1 PC	1,005.30	✓
68 BOOTLID LH HINGE	152.00	1 PC	152.00	✓
69 BOOTLID RH HINGE	152.00	1 PC	152.00	✓
70 BOOTLID UPPER LOCK	106.70	1 PC	106.70	X
71 BOOTLID WEATHER STRIP	113.10	1 PC	113.10	<i>50.00</i>
72 BOOTLID INSULATOR	26.30	1 PC	26.30	✓
73 BOOTLID INSULATOR CLIPS	4.00	8 PCS	32.00	✓
74 BOOTLID LH REFLECTOR	489.80	1 PC	489.80	✓
75 BOOTLID RH REFLECTOR	489.80	1 PC	489.80	X

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 06/10/2022

TP Veh Reg No: GBL9899C

Estimate No: ES2291063/YISHUN

Date: 17 Oct 2022

Policy No: 5130022771

Veh Reg No: SLX1217S

Make/Model: MAZDA MAZDA 3
 SEDAN 1.5 AT LED EU6

Chassis No: JM6BN22A8J0183141

Engine No: P520472853

Reg. Date: 16/03/2018

Estimate Repair Cost to Vehicle No :SLX1217S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
76 BOOTLID CENTER EMEBLEM	78.20	1 PC	78.20	✓
77 BOOTLID (MAZDA3) EMBLEM	56.10	1 PC	56.10	✓
78 BOOTLID (SKYACTIV) EMBLEM	65.80	1 PC	65.80	✓
79 REAR LH FENDER 1233	1,233.00	1 PC	1,233.00	✓
80 REAR LH FENDER INNER TRIM	190.70	1 PC	190.70	✓
81 REAR LH FENDER INNER TRIM CLIPS	4.50	8 PCS	36.00	✓
82 REAR LH FENDER UNDER LINER	162.00	1 PC	162.00	X
83 REAR LH FENDER UNDER LINER CLIPS	4.00	6 PCS	24.00	X
84 TAILLAMP LH	960.80	1 PC	960.80	✓
85 TAILLAMP PANEL LH	189.00	1 PC	189.00	✓
86 TAILLAMP RH	960.80	1 PC	960.80	X
87 REAR END PANEL 551	551.00	1 PC	551.00	✓
88 REAR END PANEL INNER TRIM	89.40	1 PC	89.40	X
89 REAR END PANEL INNER TRIM CLIPS	5.00	4 PCS	20.00	✓
90 REAR FLOORBOARD PANEL	551.00	1 PC	551.00	X
91 REAR FLOORBOARD PANEL SPONGE TRAY	398.00	1 PC	398.00	✓
92 REAR WINDSCREEN GLASS 1015.50	1,015.50	1 PC	1,015.50	✓
93 REAR WINDSCREEN GLASS MOULDING	77.00	1 PC	77.00	✓
			30,625.90	
		Less 20%	6,125.18	24,500.72
Special Net				
94 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
95 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
96 RADIATOR COOLANT	40.00	1 PC	40.00	✓
			115.00	115.00
Labour				
97 TOWING	50.00	1 LA	50.00	✓
98 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
99 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
100 REMOVE & REFIX REAR SEAT,CARPET,TOP ROOF LINING,GARNISH,ETC	120.00	1 LA	120.00	✓
101 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET,RADIATOR,SUPPORT PANEL,FRT FENDERS,TO CUT,WELD & RENEW FRT LH FENDER INNER PANEL,TO STRAIGHTEN,KNOCK & REPAIR FRT BOTH MAIN CHASSIS & REALIGN FRT THE SAME	1,600.00	1 LA	1,600.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 06/10/2022
 TP Veh Reg No: GBL9899C

Estimate No: ES2291063/YISHUN
 Date: 17 Oct 2022
 Policy No: 5130022771
 Veh Reg No: SLX1217S
 Make/Model: MAZDA MAZDA 3
 SEDAN 1.5 AT LED EU6
 Chassis No: JM6BN22A8J0183141
 Engine No: P520472853
 Reg. Date: 16/03/2018

Estimate Repair Cost to Vehicle No :SLX1217S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
102 PUTTY & RESPRAY ON FRT BUMPER,FRT BOTH FENDERS,BONNET,FRT BOTH FENDER INNER PANELS & CHASSISS,NOSE PANEL	1,200.00	1 LA	1,200.00	1100
103 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,BOOT,REAR LOCK ASSY,TO STRAIGHTEN,KNOCK & REPAIR REAR RH FENDER,CUT,WELD & RENEW REAR LH FENDER,REAR PANEL,LH TAILLAMP PANEL,REAR COMPARTMENT,TO BE CONTINUED	2,400.00	1 LA	2,400.00	1600
104 KNOCK & REPAIR REAR RH FENDER,REAR LH FENDER INNER PANEL,REAR LH MAIN CHASSISS AND REALIGN REAR PORTION		1 LA		
105 REMOVE & REFIX FUEL TANK	60.00	1 LA	60.00	✓
106 TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	280.00	1 LA	280.00	200
107 REMOVE & REFIX REVERSE CAMERA AND REVERSE SENSOR AND CHECK SYSTEM	50.00	1 LA	50.00	✓
108 PUTTY & RESPRAY ON REAR BUMPER,REAR PANEL,REAR COMPARTMENT,BOOT,HINGES,REAR BOTH FENDERS,REAR LH DOOR,REAR LH CHASSIS,REAR BUMPER REINFORCEMENT	1,700.00	1 LA	1,700.00	1400
109 TO CHECK REAR LH UNDER CARRIAGE & CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 LA	80.00	✓
110 REMOVE & INSTALL AUXILIARY BATTERY PACK & WIRE HARNESS	120.00	1 LA	120.00	80
111 TO REPROGRAMME AND RESET ECU	180.00	1 LA	180.00	80
112 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
113 RUSTPROOFING	120.00	1 LA	120.00	✓
			8,430.00	8,430.00

Total S\$ 33,045.72

Add GST @ 7% 2,313.20

Total Amount Payable S\$ 35,358.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE