

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBH4283H
Accident Date : 05-Oct-2022

No. : 06670

Date : 06-Oct-2022

Our Ref : 022162 (CHINA) / CHAN

PAGE : 1

HUI SHOON CAR RENTAL
BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C, #01-125
Singapore 575636

*Not Authorised
L1 Rep &
Resurvey After Paint
6 days*

ESTIMATED COST OF REPAIR FOR MAZDA 5 EL1628K

1 pc Rear o/s fender *2428*
1 pc Rear o/s mudflat
1 pc Rear bumper fascia
1 pc Rear o/s bumper side retainer
1 pc Rear o/s taillamp
1 pc Rear o/s fender glass seal
1 pc O/s sliding door
1 pc O/s sliding door glass
1 pc O/s sliding door frame tape

At 2,467.00
CM 59.00
mgm 962.00
Dir 48.00
sn 607.00 X
na 32.00
n 1,432.00 X
at 281.20
at 65.40

5,953.60

Less 20% : 1,190.72

1 pc Rear o/s quater glass sealant
1 pc Rear bumper reverse sensor(set)

4000-
na 60.00 sn
7 300.00 sn

To remove & refix o/s quater glass

20000
100.00 *601*

To apply undersealing

60.00 *301*

To putty and spray replaced parts

900.00 *7001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 *7001*

Total : S\$ 6,982.88

Singapore Dollars Six Thousand Nine Hundred and
Eighty Two and Cents Eighty Eight Only

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: