

22: 2:38 PM



Case Details

Case Reference Number : TAXI10/22/2026
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5248P

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19568-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompoo Insurance Singapore Pte. Ltd
Accident Date and Time : 07/10/2022 10:40 AM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

*Not Achieve
11/10/2022*

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Remarks	
Standard	Main			BUMPER REAR	1	478.90	478.90	25.00	359.17	Replace	1 <i>Re</i>	359.17	☒	
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10 <i>Re</i>	18.00	☒	
Standard	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Not Give ☒	
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Not Give ☒	
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Not Give ☒	
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Not Give ☒	
Standard	Main			ANTENNA/ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Not Give ☒	
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give ☒	
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0 <i>Re</i>	Check ☒	
Standard	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give ☒	
Standard	Main			BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	1 <i>0.1</i>	70.43	Replace ☒	
Standard	Main			BUMPER LIP REAR	1	301.90	301.90	25.00	226.42	Replace	0	0 <i>Re</i>	Check ☒	
Standard	Main			BUMPER LIP COVER RR/RH	1	155.40	155.40	25.00	116.55	Replace	0	0	Not Give ☒	
Standard	Main			UNDER COVER SUB-ASSY. RR FLOOR	1	586.10	586.10	25.00	439.58	Replace	0	0	Not Give ☒	
Standard	Main			UNDER COVER RR SHIELD	1	66.10	66.10	25.00	49.57	Replace	0	0	Not Give ☒	
Standard	Main			END PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give ☒	
Total Spare Part Cost											Surveyor Total		447.60	
Lump Sum Discount (%)											Lump Sum Dis (%)		20.00	
Final Spare Part Cost											Final Sur Total		358.08	

Minimise and max estimation now



ASS. REQ. BY:
MNEA

ASS. REQ. BY:
Hennery

REF: C71

10/10/22, 2:38 PM

<https://vacswb.smt.com.sg/Estimation.aspx>

SMRT Recommendation														
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	nn
				TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	nn
									Total Spare Part Cost	3,485.67	Surveyor Total		447.60	
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)		20.00	
									Final Spare Part Cost	2,727.46	Final Sur Total		358.08	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200.00	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY REAR PANEL	180.00	0	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			738.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	request invoice
2	Main	TO WASH AND VACUUM	80.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50.00	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			556.00	50.00	

Summary

Estimated amount and non est/Estimation note