



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/11/2022
User ID : PohSuan
Section A - Accident Details

Registration Number	SHB5248P
Case Reference Number	TAX/10/22/2026
Registration Date	19/2/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG BEE TIAM
Type of Accident	Head to Rear
Accident Date and Time	7/10/2022 6:40 PM
Accident Reported Date and Time	8/10/2022 10:17 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116520
Special Instruction to ARC, if any	TP/TOWED
Prepared Date and Time	8/10/2022 10:55 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$2,788.54	\$358.09
Total Other Cost	\$556.00	\$50.00
TOTAL COST	\$4,758.54	\$758.09
Lump Sum Total	\$4,750.00	\$800.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Somp
ARC / Surveyor Sign Off Date	10/10/2022 2:49 PM	10/10/2022 2:38 PM
Signature		
Remarks	LUMP SUM REPAIR / AFTER PAINT PHOTOS / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2211-0018	Invoice Number	
Quotation Date	02.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$556.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		90467-07211	BUMPER CLIPS (10 PCS)	10.00	\$2.40	25.00	\$18.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$234.70	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$157.90	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$208.10	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$108.70	0.00	\$0.00	Replace	Check
		52592-47021	BUMPER SEAL, RR LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$93.90	25.00	\$70.43	Replace	Replace
		76891-47020	BUMPER LIP REAR	0.00	\$301.90	0.00	\$0.00	Replace	Check
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$155.40	0.00	\$0.00	Replace	Not Given
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$586.10	0.00	\$0.00	Replace	Not Given
		51442-12210	UNDER COVER RR SHIELD	0.00	\$66.10	0.00	\$0.00	Replace	Not Given

✓
 ✓
 X
 X
 X
 X
 X
 X
 X
 X
 X
 ✓
 X
 X
 X
 X
 X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/11/2022

User ID PohSuan

		58307-47060	END PANEL	0.00	\$755.10	0.00	\$0.00	Replace	Not Given
		52563-47010	TAIL LAMP BRACKET, LH	0.00	\$35.20	0.00	\$0.00	Replace	Not Given
		81561-47170	TAIL LAMP LH	0.00	\$618.60	0.00	\$0.00	Replace	Not Given
Total					\$4,400.60		\$447.61		

X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	447.61	
	-20%	
	358.09	L/S \$800/-
	200.00	
	250.00	
	808.09	