

# ZOOM AUTOWERKS PTE LTD

## AUTOWERKS

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

\* zoomautowerks@gmail.com

17 October 2022

REG NO.: SNB 5877 C

MAKE/MODEL: MERCEDES BENZ GLC250

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY                       | DESCRIPTION                                                 | AMT(\$)                         |
|---------------------------|-------------------------------------------------------------|---------------------------------|
| <b>LIST ITEMS</b>         |                                                             |                                 |
| 1                         | Rear windscreen moulding <i>all</i>                         | 162 \$ 175.00                   |
| 1                         | Rear tailgate <i>Body</i>                                   | 3022 \$ 3,080.00                |
| 2                         | Rear tailgate dampers <i>11</i>                             | \$ 270.00 X                     |
| 2                         | Rear tailgate lamps <i>11</i>                               | \$ 690.00 X                     |
| 1                         | Rear tailgate lock <i>shotel</i>                            | 610 \$ 885.00                   |
| 1                         | Rear tailgate logo <i>all</i>                               | 75 \$ 85.00                     |
| 1                         | Rear tailgate rubber <i>11</i>                              | \$ 175.00 X                     |
| 2                         | Rear taillamps <i>11</i>                                    | \$ 1,050.00 X                   |
| 1                         | Rear end panel <i>2</i>                                     | \$ 656.00 X                     |
| 1                         | Rear end panel inner garnish <i>twi</i>                     | \$ 135.00                       |
| 1                         | Rear bumper <i>De / To. n</i>                               | \$ 1,485.00                     |
| 1                         | Rear bumper inner <i>sponge retainer cre</i>                | 182 \$ 295.00                   |
| 1                         | Rear bumper lower garnish <i>centre grazel</i>              | \$ 485.00                       |
| 2                         | Rear bumper reflectors <i>11</i>                            | \$ 210.00 X                     |
| 1                         | Rear bumper reinforcement <i>berf</i>                       | \$ 485.00                       |
| 2                         | Rear bumper side retainers <i>11</i>                        | \$ 150.00                       |
| 1                         | Rear bumper tow hook cover <i>grand</i>                     | \$ 58.00                        |
| 1                         | Rear bumper top chrome plate <i>11</i>                      | \$ 345.00 X                     |
| 4                         | Rear bumper reverse sensors <i>should</i>                   | 198 x 2 = 396 \$ 1,252.00 2 per |
| 1                         | Rear bumper lower <i>grand</i>                              | 680 \$ 710.00                   |
| 2                         | Rear fender wheel arch garnishes <i>11</i>                  | \$ 570.00 X                     |
| 2                         | Rear fender inner trims <i>11</i>                           | \$ 490.00 X                     |
|                           |                                                             | \$                              |
| Less 10%                  |                                                             | \$                              |
| <b>SPECIAL NETT ITEMS</b> |                                                             |                                 |
| 1                         | Rear windscreen sealant <i>11</i>                           | \$ 80.00 40                     |
| 1                         | Rear bumper clip (1 set) <i>11</i>                          | \$ 80.00 60                     |
|                           |                                                             | \$ 160.00                       |
| <b>LABOUR CHARGES</b>     |                                                             |                                 |
| 1                         | To remove, replaced damaged lamps and check up rear wiring. | \$ 80.00 20                     |
| 2                         | To remove and refit inner garnishes.                        | \$ 180.00 80                    |
| 3                         | To remove and refit rear reverse sensor.                    | \$ 180.00 50                    |
| 4                         | To transfer rear tailgate mechanism and wiring assembly.    | \$ 120.00 60                    |
| 5                         | To remove and refit rear windscreen glass.                  | \$ 180.00 120                   |
| 6                         | To apply undercoating.                                      | \$ 200.00 40                    |
| 7                         | Panel beating.                                              | \$ 1,600.00 580                 |
| 8                         | To re-spray painting on the affected areas.                 | \$ 1,500.00 600                 |
|                           |                                                             | \$ 4,040.00                     |

GRAND TOTAL :

*Not Arthur*  
*4 days*  
*1/5 \$ 7000*  
*10/10/22*

*198 x 2 = 396*  
*680*

*p-7925*  
*102*  
*7132.5*  
*8782.5*