



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG			Ref: CC4/ASM22009959/Rpa3q2 Date: 30/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9181B	Veh. Inspected	SND 2016E	
Policy No.	P2465703	Coverage (\$)	0.00	
Claim No.	S2M04CF0	Excess (\$)	0.00	
Assign From		Assign Date	10/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS HYBRID ELE	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MR2BZ3BE500008662	Colour	WHITE	
Odometer	86900 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	06/10/2022	Inspection Date	10/10/2022	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	