

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 12 Oct 2022

Preliminary Advice

Vehicle No	: YQ5194E	Accident Date	: 02/10/2022
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSNW00149082100
Assignment Date	: 10/10/2022	Excess	: S\$1,000.00
Date of Inspection	: 11/10/2022	Est. Duration of Repair	: 08
Inspection At	: CHENG HOE MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,960.58
Revised Amount	:S\$	4,929.58
Check Items (Estimated)	:S\$	4,975.00
Total	:S\$	9,904.58

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	31,648.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,352.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Front LH tyre found to be with tread depth about 1.6mm, still within requirement of the Road Traffic Act.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.