

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 17 Nov 2022

Preliminary Advice

Vehicle No	: YQ5194E	Accident Date	: 02/10/2022
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSNW00149082100
Assignment Date	: 10/10/2022	Excess	: S\$1,000.00
Date of Inspection	: 11/10/2022	Est. Duration of Repair	: 08
Inspection At	: CHENG HOE MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,105.58 (Est \$9,960.58 + Supp \$4,145.00)
Revised Amount	:S\$	7,434.58
Check Items (Estimated)	:S\$	6,425.00
Total	:S\$	13,859.58 (Inclusive of Supp \$3,955.00)
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000.00
COE / PARF Rebate	:S\$	31,648.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,352.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.