

REPAIR DETAILS

YQ 5194E
SUPP

Reference

Part Source: (Last Synchronised: 16 Nov 2022)
Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YQ5194E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1PC AIRCON CONDENSOR	Pu	0.00	0.00	*320.00 F ✓
2	1		*1PC AIRCON CONDENSOR FAN MOTOR ASSY		0.00	0.00	*250.00 F ?
3	1		*1PC CABIN FRT CROSSBAR	Bu	0.00	0.00	*450.00 F ?
4	1		*1 PC CABIN FRT LH MOUNTING		0.00	0.00	*280.00 F ?
5	1		*1 PC CABIN FRT RH MOUNTING		0.00	0.00	*280.00 F ?
6	1		*1 PC FRT LH WINDSCREEN PILLAR OUTER	Bu	0.00	0.00	*240.00 F ✓
7	1		*1 PC FRT LH WINDSCREEN PILLAR INNER	Bu	0.00	0.00	*210.00 F ✓
8	1		*1 PC TOP ROOF LINING	Return	0.00	0.00	*850.00 F ✓
9	1		*1 PC CABIN FRT FLOOR CROSSMEMBER	Bu	0.00	0.00	*780.00 F ✓
10	1		*1 PC CABIN FRT FLOOR LH SIDE PLATE	Bu	0.00	0.00	*105.00 F ✓
11	1		*1 PC CABIN FRT FLOOR RH SIDE PLATE	Bu	0.00	0.00	*190.00 F ✓
12	1		*1 PC CABIN FRT FLOOR LH BRACE PANEL	X	0.00	0.00	*190.00 F ?
						Total Parts (\$\$)	4,145.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Mariman e-Claims IEAS