



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHOR SAW THENG			Ref: CS/ASM22009968/Uqy3e2 Date: 23/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 2343L	Veh. Inspected	SCL 6886Y
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04CF2	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	10/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053BK4107043398	Colour	BLACK
	Odometer	247302 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
	L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/10/2022	Inspection Date	10/10/2022
	Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	