

TOTAL

		
N/S	O/S	

Veh No: SC268864 Yr Regn: 30/03/09
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota Camry c.c. 1998
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 247302 T/Radio: Insured / Std / NI / NA
Eng/No: MR053BK 4107043398
C/No: Good / Fair / Poor / Burnt
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or affected
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/57R17
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 Rear 6
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 06/10/22 D.O.I. 10/10/22
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S L & R
The U/C / Chassis frame / Body Structure affected due to collision.

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: SCL6886Y
 Vehicle Model : Toyota Camry 2.0 Auto ABS Airbag
 Manufacturing Year : 2009
 Chassis : MR053BK4107043398

not Authorized
10/10/22
2/5 \$ 9000
6 days.

S/N.	Item Description	Amount
1	Front Bumper <i>8599.85 Dis</i>	\$ 1,638.48
2	Front Bumper Clip x 1 set <i>1pc</i>	\$ 45.00
3	Front Bumper Side Retainer (RH) <i>one</i>	\$ 72.10
4	Front Bumper Chrome (RH) <i>320</i>	\$ 98.60
5	Foglamp (RH) <i>345.50 320/mis</i>	\$ 594.10
6	Foglamp Cover (RH) <i>320/mis</i>	\$ 141.57
7	Front Bumper Reinforcement <i>320</i>	\$ 387.29
8	Front Bumper Sponge <i>145.80 7011</i>	\$ 409.88
9	Front Bumper Undercover <i>7011</i>	\$ 134.50
10	Front Grille Assy <i>one</i>	\$ 566.06
11	Front Logo <i>11</i>	\$ 62.33
12	Headlamp (RH) <i>855.10 320</i>	\$ 2,483.40
13	Front Fender (RH) <i>Dis</i>	\$ 877.00
14	Front Fender Inner Garnish (RH) <i>7011</i>	\$ 159.96
15	Front Fender Inner Garnish Clip x 1 set <i>50 1pc</i>	\$ 70.00
16	"VVTI" Emblem <i>1pc</i>	\$ 43.80
17	Front Driveshaft OLS <i>1320</i>	\$ 1,199.11
18	Front Door Hinge x 2 pcs <i>11</i>	\$ 168.20
19	Front Door Lower Protector (RH) <i>11</i>	\$ 71.34
20	Front Door Trimboard Clip x 1 set <i>11</i>	\$ 50.00
21	Front Door Weatherstrip (RH) <i>11</i>	\$ 137.00
22	Side Skirt (RH) <i>7011</i>	\$ 505.80
23	Wiper Tank <i>288.50 Dis</i>	\$ 413.38
24	Front Shock Absorber (RH) <i>455.10 320</i>	\$ 528.33
25	Front Knuckle (RH) <i>485.50 320</i>	\$ 735.23
26	Front Knuckle Bearing (RH) <i>478.20 1pc</i>	\$ 190.62
27	Front Lower Arm (RH) <i>418.20 320</i>	\$ 857.63
28	Front Wheel Bearing (RH) <i>Repack</i>	\$ 141.10
29	Front Stabilizer Link (RH) <i>181.20 7011</i>	\$ 277.41
30	Front Anti-Roll Bar <i>320</i>	\$ 396.48
31	Front Crossmember <i>320/7011</i>	\$ 877.23

32	Engine Mounting (RH)	701A	\$	287.78	✓
33	Steering Rack	1755-20 501/TW1	\$	2,287.82	✓
Total :			\$	16,955.53	
Less 25%:			\$	4,238.88	
Amount :			\$	12,716.65	

S/N	Special Nett Item	Amount (\$)	
1	Front Tyre Rim (RH)	650.00	500 S/W
2	Front Tyre (RH)	350.00	120 S/W
3	Power Steering Oil	80.00	X
Amount :		\$	1,080.00

Labour	Amount (\$)	
Towing Charges	\$ 60.00	✓
To conduct 4-wheel alignment	\$ 120.00	60
To check door's and front electrical wiring system as well as focus headlamps. (Include reset/reprogramme door ECU & lock system)	\$ 300.00	20
To transfer RHF door components from old door to new door	\$ 150.00	X
To remove & reinstall RHF undercarriages	\$ 280.00	350
To remove & install steering rack and crossmember	\$ 350.00	
To remove & reinstall RHF tyre and rim, and conduct tyre balancing	\$ 80.00	X
Labour to remove, cut, change & panel beating	\$ 1,500.00	680
To putty and respray affected areas	\$ 1,600.00	1100
Labour Total :	\$ 4,440.00	
Total (Parts & Labour)	\$ 18,236.65	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-11166.37

252

8374.77

620

2270

112647.77

22

904



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CASH	DATE	Oct 20, 2022 1:00:38 PM
FIRST NAME			
LICENSE NO.	SCL 6886 Y		
MILEAGE	247332		
MAKE	CUSTOM	MODEL	TOYOTA CAMRY (V41)
NOTES			

Front Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-2.50	0.00	2.50			8.10				0.00		
PARTIAL TOE	-1.20	0.00	1.20		2.50		5.50		0.00		0.00	
SET BACK	---	---	---			-0°06"				-0°06"		
CAMBER	-1°18"	-0°32"	0°12"		-0°46"		-0°38" 0°06"		-0°48"		-0°34" 0°14"	
CASTER	1°54"	2°54"	3°54"		3°12"		2°46" 0°26"		3°12"		2°46" 0°26"	
KING-PIN	---	---	---		12°06"		11°24" 0°42"		12°06"		11°24" 0°42"	
INCL ANGLE	---	---	---		11°20"		10°44"		11°18"		10°50"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel

SPECS

DIAGNOSIS

ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.50	5.00			3.30				2.40		
PARTIAL TOE	0.00	1.20	2.50		3.20		0.00		1.20		1.20	
SET BACK	---	---	---			-0°10"				-0°10"		
CAMBER	-1°30"	-0°44"	0°00"		-1°22"		-1°26" 0°02"		-1°20"		-1°26" 0°06"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°14"				0°00"		