

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE	<b>Document No.</b>	: SQT22003053	<b>Page</b>	1
	3 ANSON ROAD #16-00	<b>Date</b>	: 18. Oct 2022		
	SPRINGLEAF TOWER	<b>Customer No.</b>	: WZC008		
	SINGAPORE 079909	<b>Svc Advisor</b>	: ANIKKA LAI SWEE KAM		
<b>Registration No</b>	: SGP6407D	<b>Engine No</b>	:		
<b>Chassis No</b>	: S00000000	<b>Date   Time</b>	: 18. Oct 2022 12:32:36 PM		
<b>Model</b>	:	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: XING DAN TRADING	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	: 3/9/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER: XING DAN TRADING						
	OWNER INSURER: AXA						
	ACC DATE: 03/09/2022						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH: SJW8972C						
<b>BO-04711-SMA-000ZZ</b>	FRT BUMPER <span style="color: blue;">X repair</span>	1	790.00	25	592.50	41.48	633.98
<b>BO-71193-SMA-003</b>	SPACER, RH, FRT BUMPER SIDE <span style="color: blue;">X NN</span>	1	38.00	25	28.50	2.00	30.50
<b>BO-71198-SMA-003</b>	SPACER, LH, FRT BUMPER SIDE <span style="color: blue;">X NN</span>	1	38.00	25	28.50	2.00	30.50
<b>BO-33101-SMA-003</b>	HEADLAMP, RH <span style="color: blue;">X NN</span>	1	635.00	25	476.25	33.34	509.59
<b>BO-60210-SMA-300ZZ</b>	FRT FENDER, R <span style="color: blue;">X repair</span>	1	529.00	25	396.75	27.77	424.52
<b>Sum Item</b>					<b>1522.50</b>	<b>106.59</b>	<b>1,629.09</b>
<b>BOSUN</b>	SUNDRIES	1	100.00 <span style="color: blue;">X</span>		100.00	7.00	107.00
<b>BML01I</b>	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00 <span style="color: blue;">X</span>		180.00	12.60	192.60
<b>BKBU01R</b>	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1500.00 <span style="color: blue;">650 ✓</span>		1500.00	105.00	1605.00
<b>BP02R</b>	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1500.00 <span style="color: blue;">1040 ✓</span>		1500.00	105.00	1605.00
<b>Sum Labor</b>					<b>3280.00</b>	<b>229.60</b>	<b>3,509.60</b>

Survey By	<u>Steve (LKK)</u>			
Date & Time	<u>01/11/22</u>	<b>Total Amount</b>	4,802.50	336.19
Excess	<u>Without Prejudice</u>	<b>Total (Inclusive of GST)</b>		<b>5,138.69</b>
Status	<u>P/P, Resurvey After Spray, 3 days</u>			

Printed on 18/10/2022 2:19:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.