

AUTOWORX HOUSE *Kp*

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

LENG HAI LIM
/o 46 Lenton Plain
Singapore 786548

Not Authorized
Running After Rain

2 days
11 Rm @ 2500k

Date: 17/10/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : MERCEDES E 200 / SMZ 6050 A	
1 pc	Rear bumper	<i>my cost</i> 1,683.40 ✓
1 pc	Rear bumper side retainer (RH)	<i>sm</i> 96.40 X
1 pc	Rear bumper corner retainer (RH)	<i>sm</i> 78.60 X
1 pc	Rear bumper park sensor (RH) <i>282.70</i>	<i>sm</i> 356.00 ✓
1 pc	Rear bumper dust cover (RH)	<i>sm</i> 258.00 X
1 pc	Rear tail lamp (RH) <i>780</i>	<i>sm</i> 842.00 ✓
	sub-total	3,314.40
	less 10%	331.44
	sub-total	2,982.96
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>2001</i> 600.00
	To check wiring system.	<i>201</i> 60.00
	To apply rust proofing on affected areas.	<i>na</i> 150.00 X
	To apply waterproof sealant on affected areas.	<i>na</i> 150.00 X
	To apply putty & spray painting on affected areas.	<i>4401</i> 650.00
	To install park sensor and ECU reset	<i>na</i> 150.00 X
	total	1,760.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: