

ASS. REC. BY:

REF: MLA / 220099911kp

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMY 1375B Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezei c.c. 1498

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 88318 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU1 1113228

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size: F: _____

R: 225/45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm

Rear R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 7/10/22 D.O.I. 11/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation

_____ \$ + RS. _____ \$

_____ \$

_____ \$

_____ \$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMY 1375B
TP/AG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2291041/YISHUN
Date: 11 Oct 2022
Policy No: 5121610405-01
Veh Reg No: SMY1375B
Make/Model: HONDA HONDA VEZEL
1.5X CVT

WS Ref: TP/AG
Claim Type: Third Party
Accident Date: 07/10/2022
TP Veh Reg No: GBD1553U

Not Authorized
U/Sup &
Resurvey After Paim
4-5 days

Chassis No: RU11113228
Engine No: L15B4033233
Reg. Date: 29/04/2016

Estimate Repair Cost to Vehicle No :SMY1375B

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	<i>Br</i> 553.60	1 PC	553.60	<i>✓</i>
2 REAR BUMPER CLIPS	<i>Nr</i> 3.90	6 PCS	23.40	<i>✓</i>
3 REAR TAILGATE	<i>Br</i> 997.60	1 PC	997.60	<i>✓</i>
4 TAILGATE EMBLEM (VEZEL)	<i>Nr</i> 43.00	1 PC	43.00	<i>✓</i>
5 TAILGATE EMBLEM (I-VTEC)	<i>Nr</i> 41.50	1 PC	41.50	<i>✓</i>
6 TAILGATE INNER LOCK	<i>Red</i> 131.00	1 PC	131.00	<i>✓</i>
7 TAILGATE INNER RUBBER	105.20	1 PC	105.20	<i>?</i>
8 REAR END PANEL	411.70	1 PC	411.70	<i>?</i>
9 REAR END PANEL INNER TOP GARNISH	<i>Red</i> 66.60	1 PC	66.60	<i>✓</i>
10 REAR WINDSCREEN GLASS MOULDING	<i>Nr</i> 138.10	1 PC	138.10	<i>✓</i>
11 RH TAILLAMP	<i>Br</i> 349.30	1 PC	349.30	<i>✓</i>
12 TAILGATE LH REFLECTOR	<i>Gr</i> 301.40	1 PC	301.40	<i>✓</i>
			3,162.40	
		Less 20%	632.48	2,529.92
Special Net				
13 REAR BUMPER LOWER SKIRT	<i>Wap</i> 320.00	1 PC	320.00	<i>✓</i>
14 REAR BUMPER TOP STICKER	<i>Nr</i> 150.00	1 PC	150.00	<i>base</i>
15 TAILGATE LOWER MOULDING	<i>Red</i> 230.00	1 PC	230.00	<i>✓</i>
16 REAR WINDSCREEN GLASS GUM	<i>Nr</i> 40.00	1 PC	40.00	<i>✓</i>
17 REVERSE SENSOR	200.00	1 SET	200.00	<i>?</i>
18 REAR NUMBER PLATE	<i>Red</i> 35.00	1 PC	35.00	<i>✓</i>
			975.00	975.00
Labour				
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	<i>✓</i>
20 PANEL BEATING	700.00	1 LA	700.00	<i>?</i>
21 PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER SIDE, LOWER SKIRT, TAILGATE	700.00	1 LA	700.00	<i>400</i>
22 REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR & RESET SYSTEM	40.00	1 LA	40.00	<i>✓</i>
23 REAR WINDSCREEN GLASS <i>RUSTPROOFING</i>	50.00	1 LA	50.00	<i>?</i>
			1,610.00	1,610.00

Total S\$ 5,114.92
Add GST @ 7% 358.04
Total Amount Payable S\$ 5,472.96

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd
[Signature]
AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/10/2022 18:24 (SGT)
Reported by	Both
Date of Accident	07/10/2022 18:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLE EXIT TO WOODLANDS AVE 12-SLIP ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMY1375B

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN CHOON SIONG
NRIC No	SXXXX395A
Email Address	angela.qmc@gmail.com
Mobile Phone No	(Phone) +65-98575789
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5121610405-01

DRIVER

Name of Driver	TAN CHOON SIONG
NRIC No	SXXXX395A
Date Of Birth	19/11/1970
Occupation	Indoor


Describe Circumstance of the Accident

** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy () Claim Third party () Reporting Only

() Claim OD/ TP at other workshop (_____)

Sketch Plan



Accident occurred on 7/10/22 @ 18:45 hrs at the above slip road. I follow front cars (X) slip due to red light on our direction. While working, m/lorry 46D 153U hit me from behind.

I was alone. No one was injured.

It was darkness during the accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Handwritten Signature]

[Handwritten Signature]

[Handwritten Signature]
YS 8/10/22

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)