COMFORTDELGRO ENGINEERING

			L	- MOITALLINIA	
Our Job Ref No : 305532165 Date 27.10.22			ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156		
FINALIZATION FORM					
To :	LKK		Fax:		
Attn : Mr	GUO QIANG				
Vehicle Reg No. SH	D8815Y	Date	of Accident : _	05.10.22	
The survey and estimates	of the repairs of the above-me	ntioned vehicle	are as follows	:-	
The repair job shall l	_	HINA		GBJ7506K	
2. The finalized amoun	t shall be:				
(a) Spare Parts a	fter List discount			and the second s	
(b) Labour Charg	es				
Total for Part	-By-Part Repair Cost				
Total for Lump	pair (if applicable) psum repair cost after Less: um Repair cost	20%		\$8,100.00	
 3. Estimated normal pe 4. We shall treat the a 7 working days 5. Thank you for your a 	bove amount as Correct an	d Confirmed If	rking days. There is no re confirm the e		
Signature :	15	_		0 QIANG NAZ LK 2/12/2022	
For Official Use Only					
ror Official Ose Offiy		T =			
Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Rental Rate P/Day		YES			
2. Loss of Income Paid	· · · ·	NO			
3. Survey Fees					
LTA Search Fee	\$7.49 / \$2.00	YES			
Medical Fees (on behalf of driver, if applicable) Overrun	ψε.τσε σε.υυ	TES			
C FULL COLUMN					
emarks:					

COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE* 05.10.22 DATE: VEHICLE NO SHD8815Y MVA **JUMANI** MAKE **MERCEDES CHINA** 05.10.22 DOA: MODEL **V-CLASS Unit Price Amount** Type Parts Description/ Labour Qty \$1,920.00 1 FRT BUMPER ASSY \$440.00 1 FRT BUMPER GRILLE LH \$1,320.00 1 FRT FENDER LH / Buc 1 FRT FENDER SHIELD LH / BR \$205.02 \$1,512.00 1 FRT WHEEL RIM / CUT 1 FRT BUMPER SIDE BRACKET LH / BR \$66.00 1 HEADLAMP ASSY LH _ CAA \$3,620.00 \$9,083.02 **SUB TOTAL** \$1,816.60 **LESS 20%** \$7,266.42 DISCOUNTED TOTAL MAXI CAP LOGO COMFORTDELGRO LOGO \$80.00 NET \$80.00 | NET \$160.00 **Labour Charge** \$1,600.00 PANEL BEATING \$1,200.00 | 1000 **SPRAY PAINT** 30 CHECK WIRING \$50.00 TUFF KOTE 40 \$50.00 **TOTAL LABOUR** \$2,900.00 **ESTIMATE TOTAL** \$10,226.42 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a nitos or surveyed after the insurance company. To resurvey before/after spray painting 48 ays. 6 L/5 6 Dif 5/10/22 To display dama, As part at during resurvey • Parts process and a confirmation • No illeg. a mo • Supple e inveyed and is subject to Surance Company Аскложиеда

Signature: Date:



VEHICLE NO.	: SHD8815Y	TYPE OF INS.	:	CHINA
JOBCARD NO.	305532165	SURVEY BY	:	LKK-GUO QIANG
ACC.DATE	05.10.22	DATE	:	

SUPPLEMENTARY OF PARTS AND LABOUR COSTS						
DESCRIPTION	QTY	ESTIMATE	REMARKS			
FRT BUMPER TRIM COVER LH	1	\$135.00	/ceA			
HEADLAMP SUPPORT PANEL	1	\$480.00	/ CRA			
FRT BUMPER MOUTING RAIL LH	1	\$45.00	MIS			
TYRE PRESSURE SENSOR	1	\$122.70	/ NEC			
	1					
	1					
CHECK ITEMS						
		Annual Control of the				

ABOUR						
		,,,,,				
	TOTAL:	\$782.70	JUMANI			