

YQ 6617X

Toyota Dyna 2754 CC.

TP China.

Xiao Tang

JHHAGV4650K002226

Rear	Number Plate	Best	30(SN)	✓
Rear	Number Plate Bracket.	Best	158.40	✓
			378.50	
Tailump	x 02	LH Cashed	$378.9 \times 2 = 757.80$	
			270.40	
Tailump	Bracket x 02	LH Dented	$270.4 \times 2 = 540.80$	
			58.10	
Tailump	Bracket Reflector x 02	LH Cashed	$58.1 \times 2 = 116.20$	
Reverse Sensor	Damaged		280(SN) 200(SN)	
Tailgate.	Dented.		1314.90	✓
			120.40	
Tailgate Hinge	x 04	2 pieces damaged	$60.2 \times 4 = 240.80$	
Tailgate Aluminium Panel		ATP new	800(SN)	X
Tailgate Aluminium Panel Rivets.			50(SN) 30(SN)	
Tailgate lower Panel.		Repair	654.30	X
Tailgate lower Lock	x 02		$279.2 \times 2 = 558.40$	
		Not new		X

YQ6617X

Toyota Sticker

155-80 ✓

Dyna Sticker

40 ✓

60km/h Sticker

NEL

15(SN) ✓

13 Pax Sticker

2496.90

15(SN) ✓

1872.67

S.N: 11190

~~1000(SN)~~ 900(SN)

Rees Under Rider. Dented

Panel Beating

~~1000~~ 600

Spray Painting

1320

~~800~~ 600

Wiring.

~~50~~ 30

To remove cruise sensor

~~100~~ 50

To spray buff coat

40 ~~180~~

total: 4382.67

2/s: 3.5K

0.4 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: