

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd
20 McCallum Street, #09-01 Tokio Marine Centre
Singapore 069046

Our File No: CS4/TMI22010003/RVY3Q2**Date:** 01/12/2022**REFERENCE**

Insured/Claimant:	200821561Z	Policy No:	MQ003159	
Date of Loss:	30/09/2022	Nature of Claim:	OD	Claim No: M2205528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB9188Z		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30181277K
Reg. Date:	14/07/2008 (Man. Year: 2008)	Chassis No:	JN1SC2F24Z0800396
Colour:	Blue	Odometer:	0 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	S\$9,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C (D)
Front Left Side:	Habilead 7 mm	Rear Left Side:	Habilead 7/7 mm
Front Right Side:	Habilead 7 mm	Rear Right Side:	Habilead 7/7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,649.22	8,649.22	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,800.00	470.00	1,330.00	73.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,460.22	9,130.22	1,330.00	12.71
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	10,460.22	6,000.00	4,460.22	42.64
+ GST 7.00/7.00% (S\$)	732.22	420.00	312.22	42.64
Nett Amount (S\$)	11,192.44	6,420.00	4,772.44	42.64

INSPECTION

Date of Assignment:	11/10/2022 Present Location:	Strides Automotive Services Pte Ltd (Woodlands)
Date Inspected:	11/10/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Dec 2022)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9188Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE WIRE HARNESS	Burnt	3,307.86 F	*3,307.86 F
2	1		*ALTERNATOR	Burnt	2,482.51 F	*2,482.51 F
3	1		*AIR CON COMPRESSOR	Burnt	1,638.87 F	*1,638.87 F
4	1		*ENGINE SEAT COVER INSULTOR	Burnt	746.00 F	*746.00 F
<u>Supplementary #1</u>						
5	1		*Discharge Hose	Burnt	250.00 F	*250.00 F
6	1		*Suction Hose	Burnt	230.00 F	*230.00 F
7	1		*Tensioner	Jammed	320.00 F	*320.00 F
8	1		*Fan Belt	Cut	155.00 F	*155.00 F
9	1		*Fuel Injector	Shorted	480.00 F	*480.00 F
F=Franchise part.						
Sub Total (\$\$)					9,610.24	9,610.24
- Add. Disc. on L,N Items 10.00/10.00% (\$\$)					961.02	961.02
Total Parts (\$\$)					8,649.22	8,649.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE ENGINE COMPARMENT DAMAGE PART DUE TO FIRE	New	1,000.00	200.00
2	TO CHECK WIRING AND OTHER ENGINE COMPARTMENT ELECTRICAL SYSTEM IS IT DAMAGE DUE TO FIRE	New	350.00	150.00
3	TOP-UP AIR CON GAS (FLASH SYSTEM AND TOP UP AIR CON OIL)	New	150.00	100.00
4	SUNDRIES	New	100.00	20.00
5	BATTERY	New	200.00	0.00
Gross Labour Cost (\$\$)			1,800.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >