

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Not followed
11/10/22
P/P 4

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3091/10/22

Your Ref:

Date: 8th OCT 2022

MR HO CHEE TUCK, PATRICK
BLK 106, #06-818,
SIMEI STREET 1, S(520106)

Take the spare part -
7 days.

Estimate cost of repair to HONDA JAZZ 1.4 (A) S/Wagon - SMU 4674 P

1 pc	tail gate door	Sub 5.00	\$	889.70	✓
1 pc	tail gate door 'JAZZ' emblem	new		35.70	✓
1 pc	tail gate door inner trim board cover	new		89.10	✓
16 pcs	tail gate door trim board clips	5.90		94.40	7
1 pc	tail gate door weatherstrip	new		93.20	✓
1 pc	tail gate door inner lock	new		118.10	✓
1 pc	tail gate door lock stricker	new		27.40	X
1 pc	rear windscreen glass moulding	new		49.50	✓
1 pc	rear windscreen glass inner dam rubber	new		38.00	✓
1 pc	rear bumper	DIY		505.00	✓
10 pcs	rear bumper clips	new	4.90	49.00	✓
2 pcs	rear bumper o/s & n/s side retainer	34.50	✓	69.00	✓
2 pcs	rear bumper o/s & n/s top retainer	32.50		65.00	?
1 pc	rear bumper centre lower garnish	new		76.00	✓
1 pc	rear bumper n/s air scoop garnish	new		41.80	✓
1 set	rear bumper o/s & n/s top reverse sensor	shrub		287.90	200 S/N
1 set	rear bumper o/s & n/s reverse sensor			287.90	?
1 pc	n/s tail lamp assy	new		325.80	✓
2 pcs	n/s tail lamp clips stopper	new	5.90	11.80	X
1 pc	n/s tail lamp panel			389.70	?
1 pc	rear n/s fender	new		692.00	X
8 pcs	rear n/s fender inner garnish clips	4.90	new	39.20	X
4 pcs	rear n/s wheel guard clips	4.90	new	19.60	X
1 pc	rear n/s fender inner garnish shield	new		155.90	X
1 pc	rear n/s fender glass inner shield	new		35.00	X
4 pcs	rear bumper o/s & n/s screw stopper	9.50	new	38.00	X
1 pc	rear end panel	Sub 5.00		388.20	✓
1 pc	rear end panel top garnish	new		68.50	✓
6 pcs	rear end panel top garnish clips	5.90		35.40	X
1 pc	rear floor board cover	new		232.20	X
1 pc	rear tool set sponge damper	new		156.30	✓
1 pc	rear floor board panel	new		893.40	X
1 pc	rear floorboard panel insulator	new		80.00	X
1 pc	tail gate door o/s handle garnish			35.20	?
				\$ 6,412.90	
Less 20%				\$ 1,282.58	
				\$ 5,130.32	
1 pc	rear windscreen glass sealant	new		50.00	S.N 40
1 pc	rear n/s fender glass sealant	new		45.00	S.N X
1 pc	rear number plate & frame	new		40.00	S.N ✓
				\$ 5,265.32	

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3091/10/22 Your Ref: Date: 8th OCT 2022

MR HO CHEE TUCK, PATRICK.,

Balance B/F..... \$ 5,265.32

To transfer tail gate door wiring system & wiring check up for affected wiring system, reverse camera, sensor.	100.00	20 120
To remove & refix tail gate door glass & rear n/s fender glass & necessary parts.	250.00	
To transfer tail gate door shock absorber, hinge, wiper motor, arm, trim board cover, inner lock, garnish, spoiler & necessary parts into new door.	180.00	60
To remove & refix fuel tank, hose, pipe & necessary parts, to enable repair rear n/s fender, rear floor board panel & necessary parts.	150.00	X
To remove & refix rear carpet, garnish, tool set, spare tyre, floor board cover, cushion seat & necessary parts.	150.00	80
To jack, straighten & knocking out rear n/s chassis frame.	300.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear n/s fender & necessary parts, to weld, renew & align above parts.	2,000.00	1000
To putty & respray painting on all affected accident parts.	2,000.00	1100
To respray Tuff-Kote on all affected accident parts.	150.00	60
To jack, straighten & knocking out rear exhaust & tail pipe.	150.00	X
	<u>\$ 10,695.32</u>	

Dollars : Ten Thousand Six Hundred Ninety Five And Cents Thirty Two Only.

HUP MOTOR TRADING & SERVICE

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: