

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAN	NCE PTE LTD	Ref:	CS/LIP22010005/Tqy3m4	
	51 CLUB STREET, LIBERTY HOUSES	#03-00 SINGAPORE 069428	Date:	04/04/2023	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMZ 468T	Veh. Inspected	SKA 4436P	
	Policy No.	SD21V08762/VPC2/R00	Coverage (\$)	0.00	
	Claim No.	AVS22/2816	Excess (\$)	0.00	
	Assign From	ANDY SEAH	Assign Date	10/10/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT 308CC	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	-	
	Chassis No.	VF34B5FVAAS209056	Colour	WHITE	
	Odometer	143589 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/40 R18	NEXEN	6 mm	
	L/H Front Tyre	235/40 R18	NEXEN	6 mm	
	R/H Rear Tyre	235/40 R18	NEXEN	6 mm	
	L/H Rear Tyre	235/40 R18	NEXEN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/09/2022	Inspection Date	11/10/2022	
	Survey held at	PROMPT AUTO SOLUTIONS PT	TE LTD		
		8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)REGISTRATION DATE: 28 FEB 2011 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			