

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : GBB7988U
 Vehicle Model : MIT. FUSO CANTER
 Accident Date : 08.10.2022
 Original Reg Date : 26.03.2010(25.03.2025)

Date : 11.10.2022
 Chassis : FB70BB1SRDEA
 TP Ins. LIBERTY

Veron

ESTIMATE

1	1 pc	Rear Silencer <i>3 ME</i>		785.20	+
2	2 pcs	Rear Silencer bracket <i>3 ME</i>	185.60	371.20	+
3	2 pcs	Rear Silencer bracket mountings <i>NEA</i>	45.00	90.00	+
4	1 pc	spare tyre carrier <i>NEA</i>		358.90	+
5	1 pc	Tailgate Frame <i>Regis Rep</i>		1,900.00	+
6	2 pc	Tailgate wheel arch garnish rear <i>NEA</i>	185.00	270.00	+
7	1 pc	Tailgate end panel <i>3 ME</i>		850.00	+
8	1 pc	Tailgate step panel <i>3 ME</i>		250.00	+
9	2 pc	Tailgate lower hood	65.00	130.00	+
10	2 pcs	Tailgate Side Handle <i>3 ME</i>	155.00	310.00	+
11	2 pcs	Tailgate Side Lock <i>3 ME</i>	120.00	240.00	+
12	2 pcs	Tailgate Side Lock Bracket <i>3 ME</i>	380.00	760.00	+
13	2 pcs	Tailgate Side Bottom Bracket <i>3 ME</i>	315.00	630.00	+
14	4 pcs	Tailgate Side Stopper <i>3 ME</i>	45.00	180.00	+
15	4 pcs	Tailgate Hinges <i>3 ME</i>	85.00	340.00	+
16	1 pc	Tailgate Bottom Cross Member <i>Regis</i>		950.00	+
17	2 pcs	Taillamps <i>cut NEA</i>	380.00	760.00	280+
18	2 pcs	Taillamps Base <i>NEA</i>	150.00	300.00	+
19	1 pc	Rear Number Plate Lamp wire hardness <i>3 ME</i>		350.00	+
20	1 pc	Rear Number Plate Lamp <i>3 ME</i>		95.00	+
			subtotal	9,920.30	
			parts disc 10 %	8,928.27	

Special Nett

1	1 set	Tailgate Outer Plate sticker <i>Rec</i>		550.00	<i>250</i>
2	1 set	Tailgate Outer Plateside reflective film <i>Rec</i>	50.00	100.00	<i>+</i>
3	1 pc	Rear number plate <i>Best</i>		50.00	<i>30.</i>
4	1 pc	Tailgate 70km/h sticker <i>Rec</i>		25.00	<i>15.</i>
5	4 pc	Tailgate stopper <i>Rec</i>	25.00	100.00	<i>+</i>
6	1 pc	Tailgate 13 pax sticker <i>Rec</i>		25.00	<i>15</i>

310

Labour charge

Panel Beating		1,600.00	<i>400</i>
Spray painting		1,600.00	<i>450.</i>
Check Wiring on tailamp		120.00	<i>30.</i>
To repair and realign rear chassis member		650.00	<i>150</i>
To remove and install rear silencer box		150.00	<i>+</i>
Anti rust		90.00	<i>40</i>

1070

Lump sum	13,988.27
-----------------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
P/P 11/10/22.

03 Days.

total: 1380 (P/P)