



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 7988U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR SILENCER	NOT NECESSARY	785.20	-
2	REAR SILENCER BRACKET @\$185.60	NOT NECESSARY	371.20	-
2	REAR SILENCER BRACKET MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	SPARE TYRE CARRIER	NOT NECESSARY	358.90	-
1	TAILGATE FRAME	TO REPAIR SEE LABOUR	1,900.00	-
2	TAILGATE WHEEL ARCH GARNISH REAR @\$185.00	NOT NECESSARY	270.00	-
1	TAILGATE END PANEL	NOT NECESSARY	850.00	-
1	TAILGATE STEP PANEL	NOT NECESSARY	250.00	-
2	TAILGATE LOWER HOOD @\$65.00	NOT NECESSARY	130.00	-
2	TAILGATE SIDE HANDLE @\$155.00	NOT NECESSARY	310.00	-
2	TAILGATE SIDE LOCK @\$120.00	NOT NECESSARY	240.00	-
2	TAILGATE SIDE LOCK BRACKET @\$380.00	NOT NECESSARY	760.00	-
2	TAILGATE SIDE BOTTOM BRACKET @\$315.00	NOT NECESSARY	630.00	-
4	TAILGATE SIDE STOPPER @\$45.00	NOT NECESSARY	180.00	-
4	TAILGATE HINGES @\$85.00	NOT NECESSARY	340.00	-
1	TAILGATE BOTTOM CROSS MEMBER	TO REPAIR SEE LABOUR	950.00	-
2	TAILLAMPS @\$380.00	NOT NECESSARY	760.00	-
2	TAILLAMPS BASE @\$150.00	NOT NECESSARY	300.00	-
1	REAR NUMBER PLATE LAMP WIRE HARDNESS	NOT NECESSARY	350.00	-
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	95.00	-
	LESS 10% DISCOUNT		-992.03	-
			8,928.27	-
<u>SPECIAL NETT ITEMS</u>				
1	SET TAILGATE OUTER PLATE STICKER (SN)	NECESSARY	550.00	250.00
1	SET TAILGATE OUTER PLATESIDE REFLECTIVE FILM @ \$50.00 (SN)	NOT NECESSARY	100.00	-
1	REAR NUMBER PLATE (SN)	BENT	50.00	30.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	25.00	15.00
4	TAILGATE STOPPER @\$25.00 (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/LIP22010006/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE 13 PAX STICKER (SN)	NECESSARY	25.00	15.00
			850.00	310.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILGATE FRAME AND TAILGATE BOTTOM CROSS MEMBER.		1,600.00	400.00
	SPRAY PAINTING.		1,600.00	450.00
	CHECK WIRING ON TAILLAMP.		120.00	30.00
	TO REPAIR AND REALIGN REAR CHASSIS MEMBER.		650.00	150.00
	TO REMOVE AND INSTALL REAR SILENCER BOX. ANTI RUST.	NOT NECESSARY	150.00	-
		90.00	40.00	
		4,210.00	1,070.00	
GRAND TOTAL			13,988.27	1,380.00
RECOMMENDED COST OF REPAIRS				1,380.00

Report Ref No. CS/LIP22010006/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.