



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LIBERTY INSURANCE PTE LTD
51 CLUB STREET, #03-00
LIBERTY HOUSESINGAPORE 069428

Ref: CS/LIP22010006/Avy3e2

Date: 20/01/2023

Code: LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 6885Z	Veh. Inspected	GBB 7988U
Policy No.		Coverage (\$)	0.00
Claim No.	IVS22/1726	Excess (\$)	0.00
Assign From	ANDY SEAH	Assign Date	10/10/2022

2. Vehicle Particulars & Condition

Make & Model	mitsubishi FB70BB1SRDEA	c.c	2977
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	FB70BBA20164	Colour	WHITE
Odometer	297767 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	RX QUEST	6 mm
L/H Front Tyre	195 R15C	RX QUEST	6 mm
R/H Rear Tyre	165 R13C	RX QUEST	6 mm
L/H Rear Tyre	165 R13C	RX QUEST	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/10/2022	Inspection Date	11/10/2022
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)REGISTRATION DATE: 26 MAR 2010
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**