

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.  
Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 12 Oct 2022

**Preliminary Advice**

Vehicle No	: SMU4897M	Accident Date	: 08/10/2022
Make	: BMW 523i	Policy No.	: SP2002752224- 01
Assignment Date	: 11/10/2022	Excess	: S\$3,100.00
Date of Inspection	: 11/10/2022	Est. Duration of Repair	: 7
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING) 176 SIN MING DRIVE #01-06, SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 21,337.60
Revised Amount	:S\$ 11,893.50
Check Items (Estimated)	:S\$ 7,224.60
Total	:S\$ 19,118.10

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 89,000.00
COE / PARF Rebate	:S\$ 27,841.00

Salvage Value	:S\$
Margin for Repair	:S\$ 61,159.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The vehicle repair on part by part basis due to no 2nd hand parts available.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.