



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET		Ref: CC4/ASM22010011/Upa3q2 Date: 04/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKH 7J	Veh. Inspected	SLE 5906K
Policy No.	GA006281	Coverage (\$)	0.00
Claim No.	S2M04CN9	Excess (\$)	0.00
Assign From		Assign Date	11/10/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6CW1071G0124110	Colour	BROWN
Odometer	55989 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	FALKEN	6 mm
L/H Front Tyre	205/55 R16	FALKEN	6 mm
R/H Rear Tyre	205/55 R16	FALKEN	6 mm
L/H Rear Tyre	205/55 R16	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/09/2022	Inspection Date	12/10/2022
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	