

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel: 6509 5521 / 65095524 Fax: 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SKH7J

*Not Addressed
Lek
7/10/22
Marcus
2/5 # 6500
4 days*

ESTIMATE

VEHICLE NO : SLE5906K
MAKE/MODEL : MAZDA 5
ACC DATE : 30.09.2022

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 TAILGATE <i>Body</i>	1,837.50	1,837.50 ✓
2	1 TAILGATE GLASS <i>11</i>	1,011.60	1,011.60 X
3	1 (SET) TAILGATE GLASS MOULDING <i>ner</i>	89.60	89.60 ✓
4	1 TAILGATE LOGO <i>ner</i>	89.50	89.50 ✓
5	1 TAILGATE EMBLEM "MAZDA" <i>ner</i>	68.60	68.60 ✓
6	1 TAILGATE EMBLEM "5" <i>ner</i>	62.60	62.60 ✓
7	1 TAILGATE EMBLEM "SKYACTIV" <i>ner</i>	89.50	89.50 ✓
8	1 TAILGATE OUTER GARNISH <i>ner</i>	491.60	491.60 ✓
9	2 TAILGATE LAMPS - RH/LH <i>o/s one</i>	421.50	843.00 <i>1pc</i>
10	2 TAILGATE LICENCE LAMPS <i>11</i>	68.20	136.40 X
11	1 TAILGATE INNER LOCK <i>no/damage</i>	280.90	280.90 ✓
12	1 TAILGATE INNER PULL POCKET <i>11</i>	86.90	86.90 X
13	1 TAILGATE INNER TRIM BOARD <i>2e/1011</i>	466.00	466.00 ✓
14	1 TAILGATE W/STRIP <i>7w1</i>	212.90	212.90 ✓
15	2 TAILGATE DAMPER <i>11</i>	210.50	421.00 X
16	2 TAILGATE STOPPER <i>11</i>	12.60	25.20 X
17	2 TAILLAMPS - RH/LH <i>o/s one</i>	765.00	1,530.00 <i>1pc</i>
18	1 REAR BUMPER <i>Dis</i>	1,027.00	1,027.00 ✓
19	2 REAR BUMPER REFLECTOR <i>o/s one</i>	86.50	173.00 <i>1pc</i>
20	1 REAR BUMPER REINFORCEMENT <i>best</i>	591.60	591.60 ✓
21	2 REAR BUMPER SIDE RETAINERS - RH/LH <i>o/s best</i>	89.50	179.00 <i>1pc</i>
22	2 REAR BUMPER TOP HOLDER <i>11</i>	48.20	96.40 X
23	1 REAR END PANEL <i>22</i>	516.00	516.00 ✓
24	1 REAR END PANEL GARNISH <i>7w1</i>	260.50	260.50 ✓
25	1 REAR FLOOR BOARD <i>11</i>	421.60	421.60 ✓
26	1 REAR FLOOR TOOLS TRAY <i>11</i>	495.00	495.00 ✓
27	1 REAR SMART KEYLESS ANTENNA <i>11</i>	191.60	191.60 ✓
			11,694.50
LESS 20%			2,338.90
			<u>9,355.60</u>

*7446.3
20%
5957.04*

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) TAILGATE GLASS SEALANT	80.00	80.00 <i>40</i>
2	1 (SET) TAILGATE GLASS FOAM TAPE	65.00	65.00 <i>40</i>
3	1 (SET) REAR BUMPER CLIP	60.00	60.00 <i>40</i>
4	1 (SET) REAR REVERSE SENSOR	280.00	280.00 <i>200</i>
5	1 REAR REVERSE CAMERA	450.00	450.00 <i>X</i>
6	1 (SET) REAR NO. PLATE	60.00	60.00 <i>40</i>
			<u>995.00</u>

<u>LABOUR CHARGES :</u>			
1	TAILGATE GLASS <i>to remove & refix</i>	180.00	180.00 <i>120</i>
2	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	150.00	150.00 <i>60</i>
3	TO CHECK REAR ELECTRICAL WIRING	50.00	50.00 <i>20</i>
4	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	80.00	80.00 <i>50</i>
5	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	120.00	120.00 <i>80</i>
6	TO TUFF KOTE	100.00	100.00 <i>60</i>
7	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,200.00	1,200.00 <i>900</i>
8	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,200.00	1,200.00 <i>600</i>
			<u>3,080.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,430.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S.N - 360
L - 1890
8/20/04
202
6560.