

Xin Yu (LKK Auto)

From: Rasul (LKKAuto)
Sent: Monday, January 30, 2023 8:48 AM
To: Xin Yu (LKK Auto)
Subject: Fw: XE3753E AFTER REPAIRED PHOTOS

case finalised

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Michael <michaelng@thinkone.com.sg>
Sent: Friday, 27 January 2023 1:12 pm
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: XE3753E AFTER REPAIRED PHOTOS

Hi Rasul.

Thank you for your email.

We accept the offer

Thank you & regards
Michael Ng

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 26 January 2023 10:05 am
To: Michael <michaelng@thinkone.com.sg>
Subject: Re: XE3753E AFTER REPAIRED PHOTOS

Hi Michael

refer to attachment

Audit parts prices required verification checked

We will be advising our principal a cost of repair L/S \$2,800.00.- with 03 days of repair, subject to their approval.

Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Michael <michaelng@thinkone.com.sg>

Sent: Wednesday, 23 November 2022 10:44 am

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: FW: XE3753E AFTER REPAIRED PHOTOS

Hi Rasul.

Attached after repaired photos for finalize.
Soonest possible

Thank you
Michael Ng