



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010024/Tqy3e2	
			Date: 16/03/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1100H	Veh. Inspected	SNA 9222X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/22/2011	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	11/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X5	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WBAZV42030LL57536	Colour	BLACK
	Odometer	86377 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/45 R20	FALKEN	6 mm
	L/H Front Tyre	255/45 R20	FALKEN	6 mm
	R/H Rear Tyre	255/45 R20	FALKEN	6 mm
	L/H Rear Tyre	255/45 R20	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2022	Inspection Date	12/10/2022
	Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	